RAYAT AL-SHARQ راية الشرق
For Trading, General Contracting, General Transportation & Inspection Services LTD Company

Al-Burjesia, Basra-Iraq
+9647703178132
+9647823386633
http://www.ras-iq.com
info@ras-iq.com

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Date of Through Examination: 14/10/2026	Date of Report: 14/10/2026	Report Number: **RAS-AM-260103035**

Description and identification of the equipment:

Lorry Loader Crane, Knuckle Boom, Diesel powered, Hydraulic Operated

Lorry Manufacturer: ACTROS
Year of Manufacture: 2012
Serial Number: WDB9502041K822006
Chassis Number: WDB9502041K822006
Plate Number: A 4081 BASRA

Name and address of employer for whom the thorough examination was made:
FALAH CO

Address of premises at which the examination was made:
RAS Yard / Al-Burjesia

Crane Model Number: F410B/450BXP25
Crane Serial Number: 4003-6237
Crane Manufacturer: FASSI
Year of Manufacture: 2009
Hook Serial Number: F-H3

Crane Capacity:
13.5 Ton
Safe Working Load (SWL):
13.5 Ton
Hook Capacity:
16.0 Ton

EXAMINED IN ACCORDING TO BS 7121-2-4:2013

Description Details of Load Test	Boom Length (m)	SWL (Kg)	Proof Load (Kg)
Load test at 100 % SWL (**Min.radius**)	**2.80**	**13500**	**NIL**
Load test at 100 % SWL (**Intermediate radius**)	**8.20**	**4650**	**4650**
Load test at 100 % SWL (**Max.radius**)	**12.20**	**3010**	**3010**

Is this the first examination after installation or assembly at a new site or location?	YES		NO	✓	**Was the examination carried out:** Within an interval of 6 months?	YES		NO	✓
					Within an interval of 12 months?	YES	✓	NO	
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES		NO	✓
					After the occurrence of exceptional circumstances?	YES		NO	✓

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons	YES		NO	✓
Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**	Yes by:			

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:
The Equipment Has Been Performance, Load & Proof Load Tested in Accordance with Standard **BS 7121-2-4:2013** and MPI Has Been Done to the Hook According to **ASTME 709.**

IS THIS EQUIPMENT SAFE TO OPERATE?	YES	✓	NO		

Name & Qualifications of person making this report: **AHMED YAHYA**	Name of person authenticating this report: Signature: **MUSTAFA SALMAN**	Latest date by which next thorough examination must be carried out: **13/10/2027**

Name and address of employer of person making and authenticating this report:
Hussein Ali Hussein, Basra, Burjesia

شركة راية الشرق
RAYAT AL-SHARQ CO.

RAYAT AL-SHARQ راية الشرق
For Trading, General Contracting, General Transportation & Inspection Services LTD Company

Al-Burjesia, Basra-Iraq
+9647703178132
+9647823386633
http://www.ras-iq.com
info@ras-iq.com

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report Number: **RAS-AM-260103035**

GENERAL DESCRIPTION OF THE EQUIPMENT	Status			
1 – OPERATOR CAB	**OK**	**NO**	**NA**	**Comments**
Manufacturer's operation manual	✓			
Load chart & operator competency certificate	✓			
Controls / marking & air condition	✓			
Window / wipers / chair / door look & seals	✓			
Body work	✓			
2 – Boom	**OK**	**NO**	**NA**	**Comments**
Base section properly attached	✓			
Boom structure	✓			
Boom angle indicator			✓	
Hoist line guides			✓	
3 – Hydraulic System	**OK**	**NO**	**NA**	**Comments**
Hydraulic oil level	✓			
Outrigger cylinders	✓			
Boom cylinder	✓			
System & Hoses	✓			
4 – Load Hook & Block	**OK**	**NO**	**NA**	**Comments**
Sheave functions smoothly			✓	
Hook rotates freely lubricated	✓			
Hook latches	✓			
5 – Drum	**OK**	**NO**	**NA**	**Comments**
Spooling of hoist lines			✓	
Drum shields cracks			✓	
Drum sides cracks			✓	
6 – Hoist line	**OK**	**NO**	**NA**	**Comments**
Overall condition			✓	
End connections			✓	
Lubricated			✓	
Clips			✓	
7 – Stabilizers	**OK**	**NO**	**NA**	**Comments**
Stabilizers beam cam	✓			
Stabilizers beam secondary locks	✓			
Stabilizers Hoses & Pipe works	✓			
8 – Loader Crane	**OK**	**NO**	**NA**	**Comments**
Operation of control levers	✓			
Attachment of loader to vehicle	✓			
Emergency Stop Switches	✓			

RAYAT AL-SHARQ راية الشرق
For Trading, General Contracting, General Transportation & Inspection Services LTD Company

Al-Burjesia, Basra-Iraq
+9647703178132
+9647823386633
http://www.ras-iq.com
info@ras-iq.com

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report Number: **RAS-AM-260103035**


9 – Safety Devices	OK	NO	NA	Comments	
Anti-two blocks system	✓				
Warning alarms	✓				
Safety equipment	✓				















RAYAT AL-SHARQ راية الشرق
For Trading, General Contracting, General Transportation & Inspection Services LTD Company

Al-Burjesia, Basra-Iraq
+9647703178132
+9647823386633
http://www.ras-iq.com
info@ras-iq.com

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report Number: **RAS-AM-260103035**

LOAD TEST & NDT (MPI) REPORT			
Report No:	260103035	Examination Date:	14/10/2026

LOAD TEST

Equipment Details		
Load Cell Serial No: 30682 / 25532	Vernier Caliper S/N: 400 0576 010	Measuring Tape S/N: N/A

NDT (MPI) FOR CRANE'S HOOK

NDT Details					
Standard:	ASTME 709	**Equipment type:**	PERMENANT YOKE	**Contrast Media:**	WHITE CONTRAST
Viewing Condition	Colored media	**Method**	WET	**Indicator:**	BLACK INK

NDT Equipment Details					
YOKE S/N	A12-512	**WHITE CONTRAST**	MagnavisWCP-2	**BLACK INK**	Magnavis7HF



Hook Details		
	Main Hook Serial Number:	F-H3
	Main Hook SWL:	16 Ton

NDT Procedure

Visual &MPI CARRIED OUT FOR THE ABOVE DESCRIPTION AND FOUND FREE OF SURFACE DEFECTS AT THE TIME OF INSPECTION

Identification of any part found to have a defect and a description of the defect: NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

ASNT Level II Inspector Name & Signature: AHMED YAHAYA	**RESULT: PASS**