


CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Certificate Page: 1 Of 3

Date of Through Examination: 16/05/2026	Date of Report: 16/05/2026	Report Number: RAS-Y-260530113
---	----------------------------	--------------------------------

Description and identification of the equipment: Forklift Truck, Diesel Powered, Hydraulically Operated	Manufacturer: Caterpillar		
	Year of Manufacture: 2007		
Model: TH580B			
Serial Number: YC5000000TBJ00199			
Chassis Number: YC5000000TBJ00199			
Name and address of employer for whom the thorough examination was made: ALYAMAMA Company	Plate Number: A1239		
Address of premises at which the examination was made: OM QASER	Max Lifting Height: 13.5 m	Safe Working Load (SWL): 5 TON	
	Center of Gravity: 600 mm	Weight: 13650 Kg	

Is this the first examination after installation or assembly at a new site or location?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	Was the examination carried out:				
					Within an interval of 6 months?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
				Within an interval of 12 months?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	
If the answer to the above question is YES, has the equipment been installed correctly?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	In accordance with an examination scheme?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
					After the occurrence of exceptional circumstances?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE									
Is the above a defect which is of immediate danger to persons						YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) NONE						Yes by:			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: NONE									
Particulars of any test carried out as part of examination: The Equipment Has been Visual, Performance and Function Tested in According to ISO 3691-1:2020 and Found Satisfactory									
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	<input type="checkbox"/>
Name & Qualifications of person making this report: Ahmed Yahya			Name of person authenticating this report: Signature: Mustafa Salman			Latest date by which next thorough examination must be carried out: 15/05/2027			
Name and address of employer of person making and authenticating this report: Hussein Ali Hussein, Basra, Burjesia									



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report number: RAS- Y-260530113

Certificate Page: 2 Of 3

GENERAL DESCRIPTION OF THE EQUIPMENT	Status			
	OK	NO	NA	Comments
1. Manufacture Data Plate	✓			
2. Forks Conditions	✓			
3. Forks Heel Wear	✓			
4. Forks – Locking Pins	✓			
5. Mast Structure & amp: Welds	✓			
6. Roller & amp: Bearing	✓			
7. Main Hoist Cylinders	✓			
8. Load Chain	✓			
9. Anchor Pins	✓			
10. Tilt Cylinder	✓			
11. Power Pack Operation	✓			
12. Engine / Motor	✓			
13. Mountings	✓			
14. Battery	✓			
15. Wiring	✓			
16. Hydraulic Pump	✓			
17. Steering Operation	✓			
18. Steering Cylinders	✓			
19. Braking System	✓			
20. Wheel Bearings	✓			
21. Tire Condition	✓			
22. Cabin Condition	✓			
23. Control Levers & amp; Pedals & amp; lights	✓			
24. Seat & Seat Belt	✓			
25. Hand Brake	✓			
26. Horn	✓			
27. Windscreen and wipers	✓			
28. Record of Major Repairs / Alterations / Replacements			✓	



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report number: RAS- Y-260530113

Certificate Page: 3 Of 3

