


CERTIFICATE OF THOROUGH EXAMINATION

This report complies with provision and use of work equipment regulations

Certificate Page: 1 Of 3

Date of Through Examination: 21/05/2026	Date of Report: 21/05/2026	Report Number: RAS-U- 2605301193
---	----------------------------	----------------------------------

Description and identification of the equipment: Wheel Loader, Diesel powered, Hydraulic Operated	Manufacturer: KAWASAKI		
	Year of Manufacture: 2019		
Model: 80V-2			
Serial Number: 8005-0707			
Name and address of employer for whom the thorough examination was made: NOJOOM AL-RUMAILA Company	Chassis Number: : 80C50707		
	Plate Number: A 94856 Basra		
Address of premises at which the examination was made: AL-ZUBAIR	Rated Operation Capacity:	Weight:	
	5000 kg Bucket Capacity: 2.5 m ³	16900 kg	

Is this the first examination after installation or assembly at a new site or location?	YES			NO			Was the examination carried out:				
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Within an interval of 6 months?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>			
If the answer to the above question is YES, has the equipment been installed correctly?	YES			NO			Within an interval of 12 months?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	In accordance with an examination scheme?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>			
				After the occurrence of exceptional circumstances?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>			

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons

YES **NO**

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**

Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

The Referenced Equipment Has Been Function Tested As per **ISO Standard 20474** and Found Satisfactory at the Time of Inspection.

IS THIS EQUIPMENT SAFE TO OPERATE?

YES **NO**

Name & Qualifications of person making this report:

Ahmed Yahya

Name of person authenticating this report:
Signature: **Mustafa Saïman**

Latest date by which next thorough examination must be carried out:

20/11/2026

Name and address of employer of person making and authenticating this report:

Hussein Ali Hussein, Basra, Burjesia



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with provision and use of work equipment regulations

Report Number: RAS-U- 2605301193

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Steps and Handholds	√				
Tires, Lug Nuts, Brakes	√				
Air reservoir	√				
Transmission	√				
Underneath of Machine	√				
Hydraulic Oil Tank	√				
Batteries & Hold Tank	√				
Fuel Tank	√				
Hydraulic cylinders, tubes, hoses and fittings	√				
Front wheel spindle bearings	√				
All-wheel drive motors	√				
Pliers linkage	√				
Pliers and end bits	√				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	√				
Engine Coolant	√				
Engine Pre-cleaner	√				
Air Filter	√				
All Hoses	√				
Radiator	√				
Engine Oil	√				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	√				
Seat Belt & Mounting	√				
Horn, backup alarm, lights	√				
Controls, gauge lenses	√				
Mechanical connections	√				
Hydraulic hoses and fittings	√				
Rams/ seals	√				



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with provision and use of work equipment regulations

Report Number: RAS-U- 2605301193

Certificate Page: 3 Of 3

