

## VISUAL & MAGNETIC PARTICLE INSPECTION REPORT

<b>Certificate No:</b> RAS-MU-2605030208		<b>Date:</b> 26/05/2026	
<b>Customer:</b> TAAM Company		<b>Due Date:</b> 25/05/2027	
<b>Location:</b> Iraq- Basra			
<b>Name and Address of Owner</b> TAAM CO		<b>Description</b> VT & MT For Hot Tapping Lifting Point	
<b>Details:</b>  <b>Serial Number:</b> PPP-2307 <b>SWL For Each Pad Eye :</b> 720 kg		<b>Area of Examination:</b> 1) FOUR LIFTING POINT	
 (A1)  (A2)  (A3)  (A4)		<b>Inspection Result:</b>  VISUAL AND MAGNETIC PARTICLE INSPECTION (MPI) HAD BEEN DONE ON WELD & CRITICAL AREAS FOR THE ABOVE DESCRIPTION <b>AND FOUND</b> VISUALLY: SURFACE INSPECTION OF WELDING.... <b>(ACCEPTED)</b> M.P.I: FREE FROM SURFACE CRACKS OR OTHER DISCONTINUITIES OF INSPECTION... <b>(ACCEPTED)</b>	
<b>Inspection Method</b> 1 - NDT (MPI Test) & Visual Test		<b>Final Results</b> <b>PASSED</b>	
<b>NDT DETAILS</b>			
<b>Equipment Type:</b> YOKE S/N: A12.512		<b>Standard:</b> ASTM E709	<b>Method:</b> WET
<b>Procedure:</b> RAS-T-21090008		<b>Indicator:</b> MAG INK	
<b>Recommendation of Certificate</b>			
This is to certify that the undersigned, a competent inspector, did attend the site for testing to examine and ascertain that this <b>Mobile Crane</b> is safe for the intended use with the limits specified providing			
Name & Qualifications of person making this report:  Ahmed Yahya		Name of person authenticating this report:  Signature: Mustafa Slaman	