

## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and Use of Work Equipment Regulations

Certificate Page: 1 Of 3

|                                          |                            |                                |
|------------------------------------------|----------------------------|--------------------------------|
| Date of Thorough Examination: 22/11/2025 | Date of Report: 22/11/2025 | Report Number: RAS-A-251130271 |
|------------------------------------------|----------------------------|--------------------------------|

|                                                                                                                                                                                                     |                                                                                                                                                                                                                             |                                                                                                       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|
| <u>Description and identification of the equipment:</u><br><br><b>Excavator Short Boom, Diesel powered, Hydraulic Operated</b>                                                                      | <b>Manufacturer:</b> HITACHI ZAXIS<br><b>Year of Manufacture:</b> 2012<br><b>Model:</b> ZX200-3<br><b>Serial Number:</b> HCM1U100T00221775<br><b>Chassis Number:</b> HCM1U100T00221775<br><b>Plate Number:</b> A 9358 BASRA | <br><b>SCAN ME</b> |
| <u>Name and address of employer for whom the thorough examination was made:</u><br><b>AL-OMRAN Company</b><br><u>Address of premises at which the examination was made:</u><br><b>HAMAR MUSHRIF</b> | <b>Max Horizontal Reach:</b><br>9.75 m<br><b>Operating Weight:</b><br>19,400 Kg                                                                                                                                             |                                                                                                       |

|                                                                                         |     |  |    |   |                                                    |     |   |    |   |
|-----------------------------------------------------------------------------------------|-----|--|----|---|----------------------------------------------------|-----|---|----|---|
| Is this the first examination after installation or assembly at a new site or location? | YES |  | NO | ✓ | <b>Was the examination carried out:</b>            |     |   |    |   |
|                                                                                         |     |  |    |   | Within an interval of 6 months?                    | YES |   | NO | ✓ |
| If the answer to the above question is YES, has the equipment been installed correctly? | YES |  | NO |   | Within an interval of 12 months?                   | YES | ✓ | NO |   |
|                                                                                         |     |  |    |   | In accordance with an examination scheme?          | YES |   | NO | ✓ |
|                                                                                         |     |  |    |   | After the occurrence of exceptional circumstances? | YES |   | NO | ✓ |

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons

YES ☐ NO ☒

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**

Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

The Referenced Equipment Has Been Function Tested As per ISO 20474-5:2017 and Found Satisfactory at the Time of Inspection.

**IS THIS EQUIPMENT SAFE TO OPERATE?**

YES ☒ NO ☐

Name & Qualifications of person making this report:  
**Ahmed Yahya**

Name of person authenticating this report:  
Signature: **Mustafa Salman**

Latest date by which next thorough examination must be carried out:  
**21/11/2026**

Name and address of employer of person making and authenticating this report:  
**Hussein Ali Hussein, Basra, Burjesia**



## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and Use of Work Equipment Regulations

Report Number: **RAS-A-251130271**

Certificate Page: 2 Of 3

| 1- FROM GROUND               |           |      |                   |         |          |
|------------------------------|-----------|------|-------------------|---------|----------|
|                              | Condition |      | Corrective Action |         | Comments |
|                              | Pass      | Fail | Repair            | Replace |          |
| General                      | ✓         |      |                   |         |          |
| Axle System                  | ✓         |      |                   |         |          |
| Chain Belt                   | ✓         |      |                   |         |          |
| Tires and Wheels             | N/A       |      |                   |         |          |
| Hydraulic System             | ✓         |      |                   |         |          |
| Steering System              | ✓         |      |                   |         |          |
| Brake System                 | ✓         |      |                   |         |          |
| Chassis Condition            | ✓         |      |                   |         |          |
| Electrical System            | ✓         |      |                   |         |          |
| Reverse Alarm                | ✓         |      |                   |         |          |
| Signal Light                 | ✓         |      |                   |         |          |
| Wind Shield                  | ✓         |      |                   |         |          |
| Glasses & Mirrors            | ✓         |      |                   |         |          |
| Cutting Edge                 | ✓         |      |                   |         |          |
| 2- ENGINE COMPARTMENT        |           |      |                   |         |          |
|                              | Condition |      | Corrective Action |         | Comments |
|                              | Pass      | Fail | Repair            | Replace |          |
| Engine Oil                   | ✓         |      |                   |         |          |
| Engine Coolant               | ✓         |      |                   |         |          |
| Engine Pre-cleaner           | ✓         |      |                   |         |          |
| Air Filter                   | ✓         |      |                   |         |          |
| All Hoses                    | ✓         |      |                   |         |          |
| Radiator                     | ✓         |      |                   |         |          |
| Engine Oil                   | ✓         |      |                   |         |          |
| 3- OPERATOR CAB              |           |      |                   |         |          |
|                              | Condition |      | Corrective Action |         | Comments |
|                              | Pass      | Fail | Repair            | Replace |          |
| Seat                         | ✓         |      |                   |         |          |
| Seat Belt & Mounting         | ✓         |      |                   |         |          |
| Horn, backup alarm, lights   | ✓         |      |                   |         |          |
| Controls, gauge lenses       | ✓         |      |                   |         |          |
| Mechanical connections       | ✓         |      |                   |         |          |
| Hydraulic hoses and fittings | ✓         |      |                   |         |          |



## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and Use of Work Equipment Regulations

Report Number: **RAS-A-251130271**

Certificate Page: 3 Of 3

