

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Certificate Page: 1 Of 3

Date of Thorough Examination: 24/02/2026	Date of Report: 24/02/2026	Report Number: RAS-C-260330162
--	----------------------------	---------------------------------------

<u>Description and identification of the equipment:</u> Man Lift Basket, Diesel powered, Hydraulic Operated	<u>Manufacturer:</u> HYUNDAI <u>Year of Manufacture:</u> 2018 <u>Model:</u> HYUNDAI <u>Serial Number:</u> KN95J7MJD6NB5E004 <u>Chassis Number:</u> KN95J7MJD6NB5E004 <u>Plate Number:</u> A 90751 Basra		
<u>Name and address of employer for whom the thorough examination was made:</u> HASSAN NASSIR <u>Address of premises at which the examination was made:</u> ABO SUKHAIR	<u>Basket Manufacture:</u> NOVAS <u>Year of Manufacture:</u> 2010 <u>Model:</u> NVS 350 <u>Serial Number:</u> NVS-100-406	<u>Working Height:</u> 40.0 m <u>Horizontal Reach:</u> 36.0 m <u>Safe Working Load (SWL):</u> 300 Kg <u>MAX REDUIS:</u> 24 M	

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	YES	NO
			Within an interval of 6 months?	Within an interval of 12 months?
			YES	YES
			NO	NO
			✓	✓
If the answer to the above question is YES, has the equipment been installed correctly?	YES	NO	In accordance with an examination scheme?	After the occurrence of exceptional circumstances?
			YES	YES
			NO	NO
			✓	✓

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons

YES NO ✓

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**

Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

The Referenced Equipment Has Been Function Tested As per **EN 280-1:2022** and Found Satisfactory at the Time of Inspection.

IS THIS EQUIPMENT SAFE TO OPERATE?	YES	✓	NO
---	-----	---	----

Name & Qualifications of person making this report: Ahmed Yahya	Name of person authenticating this report: Signature: Mustafa Salman	Latest date by which next thorough examination must be carried out: 23/08/2026
---	--	--

Name and address of employer of person making and authenticating this report:
Hussein Ali Hussein, Basra, Burjesia



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report Number: RAS-C-260330162

Certificate Page: 2 Of 3

GENERAL DESCRIPTION OF THE EQUIPMENT	Status			
	OK	NO	NA	Comments
Axle System	✓			
Tires and Wheels	✓			
Steering System	✓			
First Aid Kit	✓			
Brake System	✓			
Chassis Condition	✓			
Electrical System	✓			
Lifting Arm Jack	✓			
Reverse Alarm	✓			
Signal Light	✓			
Wind Shield	✓			
Glasses & Mirrors	✓			
Transmission	✓			
Operational Control	✓			
Cabin Condition	✓			
Fire Extinguisher	✓			
Leaks	✓			
Cracks	✓			
Pressure Reading	✓			
Control Operation	✓			
Standing Legs	✓			
Sand Pads	✓			
Harness Anchorage Points (Fitting & Condition)	✓			
Over Load Warning System	✓			
Emergency Lowering System	✓			
Emergency Stop Button	✓			
Boom Condition	✓			
Spark Arrester	✓			
Fuel Tank	✓			
Alarm Light	✓			
Engine Oil	✓			
Engine Coolant	✓			
Engine Pre-cleaner	✓			
Air Filter	✓			
All Hoses	✓			
Name & Qualifications of person making this report:				
Ahmed Yahya				



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report Number: **RAS-C-260330162**

Certificate Page: 3 Of 3

	OK	NO	NA	Comments
Radiator	✓			
Seat	✓			
Seat Belt	✓			
Mounting	✓			
Horn	✓			
Backup Alarm	✓			
Lights	✓			
Controls	✓			
Gauge lenses	✓			
Mechanical connections	✓			
Hydraulic hoses	✓			
Fittings	✓			
Rams	✓			
Seals	✓			
Level Gauge	✓			

