


VISUAL & MAGNETIC PARTICLE INSPECTION REPORT

Certificate No: RAS-U-2604501059		Date: 22/4/2026
Customer: MCC Company		Due Date: 21/10/2026
Location: Iraq- Basra		
Name and Address of Owner MCC / SOUTH RUMAILA		Description Lifting Basket C\W 6 Lifting Pad eyes
Serial Number: MCC-B-04	Area of Examination: 4 Welded Lifting Points	
		Inspection Result: VISUAL AND MAGNETI PARTICLE INSPECTION (MPI) HAD BEEN DONE ON WELD & CRITICAL AREAS FOR THE ABOVE DESCRIBSION AND FOUND VISUALY: SURFACE INSPECTION OF WELDING.... (ACCEPTED) M.P.I: FREE FROM SURFACE CRACKS OR OTHER DISCONTINUNTIES OF INSPECTION... (ACCEPTED)
Inspection Method 1 - NDT (MPI Test) & Visual Test		Final Results PASSED
NDT DETAILS		
Equipment Type: YOKE S/N: A12.512	Standard: ASTM E709	Method: WET
Procedure: RAS-T-21090008	Indicator: MAG INK	
Recommendation of Certificate		
This is to certify that the undersigned, a competent inspector, did attend the site for testing to examine and ascertain that this Hopper is safe for the intended use with the limits specified providing		
Name & Qualifications of person making this report: Mustafa Salman 		Name of person authenticating this report: Signature: Ahmed Yahya 