

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Certificate Page: 1 Of 3

Date of Thorough Examination: 20/06/2026		Date of Report: 20/02/2026		Report Number: RAS-C-260630289																																		
<u>Description and identification of the equipment:</u> Man Lift Basket (MEWP), Diesel powered, Hydraulic Operated			Manufacturer: GENIE Year of Manufacture: 2016 Model: S-85 Serial Number: S8016 - 5940 Chassis Number: N/A Plate Number: N/A																																			
<u>Name and address of employer for whom the thorough examination was made:</u> Al-Manabaa Al-Khadhraa Company <u>Address of premises at which the examination was made:</u> Al-Zubair			Safe Working Load (SWL): 227 Kg As per Load Chart Specification Total Weight: 16445 Kg																																			
			Working Height: 24.4 m Horizontal Reach: 18.3 m																																			
Is this the first examination after installation or assembly at a new site or location?			Was the examination carried out?																																			
			<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> <tr> <td colspan="4">Within an interval of 6 months?</td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> <tr> <td colspan="4">Within an interval of 12 months?</td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> <tr> <td colspan="4">In accordance with an examination scheme?</td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> <tr> <td colspan="4">After the occurrence of exceptional circumstances?</td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> </table>			YES		NO	✓	Within an interval of 6 months?				YES		NO	✓	Within an interval of 12 months?				YES		NO	✓	In accordance with an examination scheme?				YES		NO	✓	After the occurrence of exceptional circumstances?				YES
YES		NO	✓																																			
Within an interval of 6 months?																																						
YES		NO	✓																																			
Within an interval of 12 months?																																						
YES		NO	✓																																			
In accordance with an examination scheme?																																						
YES		NO	✓																																			
After the occurrence of exceptional circumstances?																																						
YES		NO	✓																																			
If the answer to the above question is YES, has the equipment been installed correctly?			<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td></td> </tr> <tr> <td colspan="4">In accordance with an examination scheme?</td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> <tr> <td colspan="4">After the occurrence of exceptional circumstances?</td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> </table>			YES		NO		In accordance with an examination scheme?				YES		NO	✓	After the occurrence of exceptional circumstances?				YES		NO	✓													
YES		NO																																				
In accordance with an examination scheme?																																						
YES		NO	✓																																			
After the occurrence of exceptional circumstances?																																						
YES		NO	✓																																			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE																																						
Is the above a defect which is of immediate danger to persons					YES ☐ NO ☒																																	
Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) NONE					Yes by:																																	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: NONE																																						
Particulars of any test carried out as part of examination: The Referenced Equipment Has Been Function Tested As per EN 280-1:2022 and Found Satisfactory at the Time of Inspection.																																						
IS THIS EQUIPMENT SAFE TO OPERATE?				YES ☒	NO ☐																																	
Name & Qualifications of person making this report: Ahmed Yahya		Name of person authenticating this report: Mustafa Salman		Latest date by which next thorough examination must be carried out: 19/12/2026																																		
Name and address of employer of person making and authenticating this report: Hussein Ali Hussein, Basra, Burjesia																																						



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Equipment Engineers Association Technical requirements

Report Number: RAS-C-260630289

Certificate Page: 2 Of 3

GENERAL DESCRIPTION OF THE EQUIPMENT	Status			
	OK	NO	NA	Comments
Axle System	✓			
Tires and Wheels	✓			
Steering System	✓			
First Aid Kit	✓			
Brake System	✓			
Chassis Condition	✓			
Electrical System	✓			
Lifting Arm Jack	✓			
Reverse Alarm	✓			
Signal Light	✓			
Wind Shield			✓	
Glasses & Mirrors			✓	
Transmission	✓			
Operational Control	✓			
Cabin Condition			✓	
Fire Extinguisher	✓			
Leaks	✓			
Cracks	✓			
Pressure Reading	✓			
Control Operation	✓			
Standing Legs			✓	
Sand Pads			✓	
Over Load Warning System	✓			
Emergency Lowering System	✓			
Emergency Stop Button	✓			
Boom Condition	✓			
Spark Arrester	✓			
Fuel Tank	✓			
Alarm Light	✓			
Engine Oil	✓			
Engine Coolant	✓			
Engine Pre-cleaner	✓			
Air Filter	✓			
All Hoses	✓			



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Equipment Engineers Association Technical requirements

Report Number: RAS-C-260630289

Certificate Page: 3 Of 3

	OK	NO	NA	Comments
Radiator	✓			
Seat			✓	
Seat Belt			✓	
Mounting			✓	
Horn	✓			
Backup Alarm	✓			
Lights	✓			
Controls	✓			
Gauge lenses	✓			
Mechanical connections	✓			
Hydraulic hoses	✓			
Fittings	✓			
Rams	✓			
Seals	✓			
Level Gauge	✓			

