

VISUAL & MAGNETIC PARTICLE INSPECTION REPORT

Certificate No: RAS-Y-260650221		Date: 03/06/2026	
Customer: ALYAMAMA Company		Due Date: 02/12/2026	
Location: Iraq- Basra			
Name and Address of Owner OM-QASR		Description Examination of Welded Joints	
		Area of Examination: Twenty-Five (25) Welded Joints local Structural Steel Located on Frame Connections.	
		Inspection Result: VISUAL AND MAGNETIC PARTICLE INSPECTION (MPI) HAD BEEN DONE ON WELD & CRITICAL AREAS FOR THE ABOVE DESCRIPTION AND FOUND VISUALY: SURFACE INSPECTION OF WELDING.... (ACCEPTED) M.P.I: FREE FROM SURFACE CRACKS OR OTHER DISCONTINUITIES OF INSPECTION... (ACCEPTED)	
Inspection Method 1 - NDT (MPI Test) & Visual Test		Final Results PASSED	
NDT DETAILS			
Equipment Type: YOKE S/N: A12.512		Standard: ASTM E709	Method: WET
Procedure: RAS-T-21090008		Indicator: MAG INK	
Recommendation of Certificate			
This is to certify that the undersigned, a competent inspector, did attend the site for testing to examine and ascertain that this PIPE LINE W&A is safe for the intended use with the limits specified providing			
Name & Qualifications of person making this report: AHMED YAHYA		Name of person authenticating this report: MUSTAFA SALMAN	

