



THROUGH VISUAL & MAGNETIC PARTICLE INSPECTION REPORT

Certificate No: RAS-C-260650316		Date: 29/June/2026	
Customer: Al-Sayer Company		Due Date: 28/December/2026	
Location: Iraq- Baghdad			
Name and Address of Owner BAGHDAD		Type Lifting Point Welded Caravan	
Serial Number: AS04			
Quantity 04 Lifting Points For 1 Caravan		DIM: (2.5×3×6) m	
		Inspection Result: VISUAL AND MAGNETIC PRATICLE INSPECTION (M.P.I) HAD BEEN DONE ON WELD, FORGN & CRITICAL AREAS FOR THE ABOVE DESCRIPTION <u>AND FOUND</u> VISUALLY: SURFACE INSPECTION OF WELDING.... (ACCEPTED) M.P.I: FREE FROM SURFACE CRACKS OR ANY OTHER DISCONTINUITIES AT TIME OF INSPECTION...(ACCEPTED)	
Inspection Method 1 - (MPI Test) & Visual Test		Final Results PASSED	
NDT DETAILS			
Equipment Type: YOKE S/N: A12.512		Standard: ASTM E709	Method: WET
Indicator: MAG INK			
Recommendation of Certificate			
This is to certify That the undersigned, a competent inspector, did, attend the site for testing to examine and ascertain that this Lifting Point Welded Caravan is safe for the intended use with the limits specified providing.			
Name & Qualifications of person making this report: Ahmed Yahya 		Name of person authenticating this report: Signature: Mustafa Salman 	
Name and address of employer of persons making and authenticating this report: Hussein Ali Hussein, Basra, Burjesia			

