

VISUAL & MAGNETIC PARTICLE INSPECTION REPORT

Certificate No: RAS-Y-260650402 Customer: IGCC Location: Iraq- Basra		Date: 30/06/2026 Due Date: 29/12/2026	
Name and Address of Owner Lp Flare		Description 4 LIFTING POINT FOR CARAVAN (TOILET)	
		Area of Examination: LIFTING POINT FOR CARAVAN Serial Number: 03090 Quantity: 4	
		Inspection Result: VISUAL AND MAGNETIC PARTICLE INSPECTION (MPI) HAD BEEN DONE ON WELD & CRITICAL AREAS FOR THE ABOVE DESCRIPTION AND FOUND VISUALY: SURFACE INSPECTION OF WELDING.... (ACCEPTED) M.P.I: FREE FROM SURFACE CRACKS OR OTHER DISCONTINUITIES OF INSPECTION... (ACCEPTED)	
Inspection Method 1 - NDT (MPI Test) & Visual Test		Final Results PASSED	
NDT DETAILS			
Equipment Type: YOKE S/N: A12.512		Standard: ASTM E709	Method: MPI
Procedure: RAS-T-21090008		Indicator: MAG INK	
Recommendation of Certificate			
This is to certify that the undersigned, a competent inspector, did attend the site for testing to examine and ascertain that this LIFTING POINT FOR CARAVAN (TOILET) is safe for the intended use with the limits specified providing			
Name & Qualifications of person making this report: AHMED YAHYA		Name of person authenticating this report: MUSTAFA SALMAN 	

