

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Equipment Engineers Association Technical requirements

Certificate Page: 1 Of 3

Date of Through Examination: 25/04/2026	Date of Report: 25/04/2026	Report Number: RAS-Y-26043087
---	----------------------------	--------------------------------------

<u>Description and identification of the equipment:</u> Bulldozer Truck, Diesel powered, Hydraulic Operated	<u>Manufacturer:</u> Caterpillar <u>Year of Manufacture:</u> 2001 <u>Model:</u> D65 <u>Serial Number:</u> D65EX12/62313 <u>Chassis Number:</u> D65EX12/62313 <u>Plate Number:</u> 14 B4109	
<u>Name and address of employer for whom the thorough examination was made:</u> Al-Yamama Company <u>Address of premises at which the examination was made:</u> Omqasr	<u>Weight:</u> 19 Ton	

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out:				
	YES		NO	✓	Within an interval of 6 months?	YES		NO	✓
					Within an interval of 12 months?	YES	✓	NO	
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES		NO	✓
					After the occurrence of exceptional circumstances?	YES		NO	✓

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons

YES ☐ NO ☒

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**

Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

The Equipment has been visually examined and function tested according to BS EN 474-2:2022 general requirement

IS THIS EQUIPMENT SAFE TO OPERATE?

YES ☒ NO ☐

Name & Qualifications of person making this report: Ahmed Yahya	Name of person authenticating this report: Signature: Mustafa Salman	Latest date by which next thorough examination must be carried out: 24/04/2027
---	--	--

Name and address of employer of person making and authenticating this report:
Hussein Ali Hussein, Basra, Burjesia



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Equipment Engineers Association Technical requirements

RAS-Y-26043087

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
General	✓				
Axle System	✓				
Chain Belt	✓				
Track chains, Rollers, Sprocket, Final Drive	✓				
Hydraulic System	✓				
Steering System	✓				
Brake System	✓				
Chassis Condition	✓				
Electrical System	✓				
Reverse Alarm	✓				
Signal Light	✓				
Wind Shield	✓				
Glasses & Mirrors	✓				
Cutting Edge	✓				
Crack, Covers, Damage	✓				
Leaks, Wears	✓				
Ripper, Push frame, Tilt Cylinder, Lift Cylinder	✓				
Transmission, Blade, Front idler	✓				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	✓				
Engine Coolant	✓				
Engine Pre-cleaner	✓				
Air Filter	✓				
All Hoses	✓				
Radiator	✓				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	✓				
Seat Belt & Mounting	✓				
Horn, backup alarm, lights	✓				
Controls, gauge lenses	✓				
Mechanical connections	✓				
Hydraulic hoses and fittings	✓				



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Equipment Engineers Association Technical requirements

RAS-Y-26043087

Certificate Page: 3 Of 3

