

## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Equipment Engineers Association Technical requirements

Certificate Page: 1 Of 3

|                                         |                            |                               |
|-----------------------------------------|----------------------------|-------------------------------|
| Date of Through Examination: 04/05/2026 | Date of Report: 04/05/2026 | Report Number: RAS-Y-26043096 |
|-----------------------------------------|----------------------------|-------------------------------|

|                                                                                                                                                                                               |                                                                                                                                                                                                |                                                                                     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| <u>Description and identification of the equipment:</u><br><br><b>Bulldozer Truck, Diesel powered, Hydraulic Operated</b>                                                                     | <b>Manufacturer:</b> KOMATSU<br><b>Year of Manufacture:</b> 1996<br><b>Model:</b> D65-6<br><b>Serial Number:</b> 32650<br><b>Chassis Number:</b> 65-6-32650<br><b>Plate Number:</b> 11 N 62818 |  |
| <u>Name and address of employer for whom the thorough examination was made:</u><br><b>Al-Yamama Company</b><br><u>Address of premises at which the examination was made:</u><br><b>Omqasr</b> | <b>Weight:</b><br>19 Ton                                                                                                                                                                       |                                                                                     |

|                                                                                         |     |  |    |   |                                                    |     |   |    |   |
|-----------------------------------------------------------------------------------------|-----|--|----|---|----------------------------------------------------|-----|---|----|---|
| Is this the first examination after installation or assembly at a new site or location? |     |  |    |   | Was the examination carried out:                   |     |   |    |   |
|                                                                                         | YES |  | NO | ✓ | Within an interval of 6 months?                    | YES |   | NO | ✓ |
|                                                                                         |     |  |    |   | Within an interval of 12 months?                   | YES | ✓ | NO |   |
| If the answer to the above question is YES, has the equipment been installed correctly? | YES |  | NO |   | In accordance with an examination scheme?          | YES |   | NO | ✓ |
|                                                                                         |     |  |    |   | After the occurrence of exceptional circumstances? | YES |   | NO | ✓ |

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons **YES** ☐ **NO** ☒

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE** Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

**The Equipment has been visually examined and function tested according to BS EN 474-2:2022 general requirement**

**IS THIS EQUIPMENT SAFE TO OPERATE?** **YES** ☒ **NO** ☐

|                                                                           |                                                                                |                                                                                          |
|---------------------------------------------------------------------------|--------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|
| Name & Qualifications of person making this report:<br><b>Ahmed Yahya</b> | Name of person authenticating this report:<br>Signature: <b>Mustafa Salman</b> | Latest date by which next thorough examination must be carried out:<br><b>03/05/2027</b> |
|---------------------------------------------------------------------------|--------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|

Name and address of employer of person making and authenticating this report:  
**Hussein Ali Hussein, Basra, Burjesia**



## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Equipment Engineers Association Technical requirements

RAS-Y-26043096

Certificate Page: 2 Of 3

| 1- FROM GROUND                                   |           |      |                   |         |          |
|--------------------------------------------------|-----------|------|-------------------|---------|----------|
|                                                  | Condition |      | Corrective Action |         | Comments |
|                                                  | Pass      | Fail | Repair            | Replace |          |
| General                                          | ✓         |      |                   |         |          |
| Axle System                                      | ✓         |      |                   |         |          |
| Chain Belt                                       | ✓         |      |                   |         |          |
| Track chains, Rollers, Sprocket, Final Drive     | ✓         |      |                   |         |          |
| Hydraulic System                                 | ✓         |      |                   |         |          |
| Steering System                                  | ✓         |      |                   |         |          |
| Brake System                                     | ✓         |      |                   |         |          |
| Chassis Condition                                | ✓         |      |                   |         |          |
| Electrical System                                | ✓         |      |                   |         |          |
| Reverse Alarm                                    | ✓         |      |                   |         |          |
| Signal Light                                     | ✓         |      |                   |         |          |
| Wind Shield                                      | ✓         |      |                   |         |          |
| Glasses & Mirrors                                | ✓         |      |                   |         |          |
| Cutting Edge                                     | ✓         |      |                   |         |          |
| Crack, Covers, Damage                            | ✓         |      |                   |         |          |
| Leaks, Wears                                     | ✓         |      |                   |         |          |
| Ripper, Push frame, Tilt Cylinder, Lift Cylinder | ✓         |      |                   |         |          |
| Transmission, Blade, Front idler                 | ✓         |      |                   |         |          |
| 2- ENGINE COMPARTMENT                            |           |      |                   |         |          |
|                                                  | Condition |      | Corrective Action |         | Comments |
|                                                  | Pass      | Fail | Repair            | Replace |          |
| Engine Oil                                       | ✓         |      |                   |         |          |
| Engine Coolant                                   | ✓         |      |                   |         |          |
| Engine Pre-cleaner                               | ✓         |      |                   |         |          |
| Air Filter                                       | ✓         |      |                   |         |          |
| All Hoses                                        | ✓         |      |                   |         |          |
| Radiator                                         | ✓         |      |                   |         |          |
| 3- OPERATOR CAB                                  |           |      |                   |         |          |
|                                                  | Condition |      | Corrective Action |         | Comments |
|                                                  | Pass      | Fail | Repair            | Replace |          |
| Seat                                             | ✓         |      |                   |         |          |
| Seat Belt & Mounting                             | ✓         |      |                   |         |          |
| Horn, backup alarm, lights                       | ✓         |      |                   |         |          |
| Controls, gauge lenses                           | ✓         |      |                   |         |          |
| Mechanical connections                           | ✓         |      |                   |         |          |
| Hydraulic hoses and fittings                     | ✓         |      |                   |         |          |



## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Equipment Engineers Association Technical requirements

RAS-Y-26043096

Certificate Page: 3 Of 3

