

## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

Certificate Page: 1 Of 3

|                                         |                            |                                       |
|-----------------------------------------|----------------------------|---------------------------------------|
| Date of Through Examination: 25/05/2026 | Date of Report: 25/05/2026 | Report Number: <b>RAS-Y-260630123</b> |
|-----------------------------------------|----------------------------|---------------------------------------|

|                                                                                                                                                                                               |                                                                                                                                                                                                                      |                                                                                     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| <u>Description and identification of the equipment:</u><br><br><b>Water Tanker Truck fitted with Water Jet, Diesel powered, Hydraulic Operated</b>                                            | <b>Manufacturer:</b> MERCEDES-BENZ<br><b>Year of Manufacture:</b> 2007<br><b>Model:</b> 930.16<br><b>Serial Number:</b> WDAKHCAA47L148805<br><b>Chassis Number:</b> WDAKHCAA47L148805<br><b>Plate Number:</b> A 4045 |  |
| <u>Name and address of employer for whom the thorough examination was made:</u><br><b>Al-Yamama Company</b><br><u>Address of premises at which the examination was made:</u><br><b>Omqasr</b> | <b>Capacity:</b><br>20000 Ltr                                                                                                                                                                                        | <b>Weight:</b><br>40000 KG                                                          |

### Standard: BS 474-1:2022

| Is this the first examination after installation or assembly at a new site or location? | Was the examination carried out? |    |                                                    |    |
|-----------------------------------------------------------------------------------------|----------------------------------|----|----------------------------------------------------|----|
|                                                                                         | YES                              | NO | YES                                                | NO |
|                                                                                         |                                  |    | Within an interval of 6 months?                    |    |
|                                                                                         |                                  |    | Within an interval of 12 months?                   |    |
| If the answer to the above question is YES, has the equipment been installed correctly? | YES                              | NO | In accordance with an examination scheme?          |    |
|                                                                                         |                                  |    | After the occurrence of exceptional circumstances? |    |

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons

YES NO

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**

Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

The equipment has been visual and function Tested to **BS 474-1:2022** & Found Satisfactory at the Time of Inspection.

**IS THIS EQUIPMENT SAFE TO OPERATE?** YES NO

|                                                                           |                                                                                |                                                                                          |
|---------------------------------------------------------------------------|--------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|
| Name & Qualifications of person making this report:<br><b>Ahmed Yahya</b> | Name of person authenticating this report:<br>Signature: <b>Mustafa Salman</b> | Latest date by which next thorough examination must be carried out:<br><b>24/05/2027</b> |
|---------------------------------------------------------------------------|--------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|

Name and address of employer of person making and authenticating this report:

**Hussein Ali Hussein, Basra, Burjesia**



## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

RAS-Y-260630123

Certificate Page: 2 Of 3

| 1- FROM GROUND               |           |      |                   |         |          |
|------------------------------|-----------|------|-------------------|---------|----------|
|                              | Condition |      | Corrective Action |         | Comments |
|                              | Pass      | Fail | Repair            | Replace |          |
| Axle System                  | ✓         |      |                   |         |          |
| Tires and Wheels             | ✓         |      |                   |         |          |
| Steering System              | ✓         |      |                   |         |          |
| Brake System                 | ✓         |      |                   |         |          |
| Chassis Condition            | ✓         |      |                   |         |          |
| Tailgate                     | ✓         |      |                   |         |          |
| Electrical System            | ✓         |      |                   |         |          |
| Tank Condition               | ✓         |      |                   |         |          |
| Reverse Alarm                | ✓         |      |                   |         |          |
| Signal Light                 | ✓         |      |                   |         |          |
| Wind Shield                  | ✓         |      |                   |         |          |
| Glasses & Mirrors            | ✓         |      |                   |         |          |
| Transmission                 | ✓         |      |                   |         |          |
| 2- ENGINE COMPARTMENT        |           |      |                   |         |          |
|                              | Condition |      | Corrective Action |         | Comments |
|                              | Pass      | Fail | Repair            | Replace |          |
| Engine Oil                   | ✓         |      |                   |         |          |
| Engine Coolant               | ✓         |      |                   |         |          |
| Engine Pre-cleaner           | ✓         |      |                   |         |          |
| Air Filter                   | ✓         |      |                   |         |          |
| All Hoses                    | ✓         |      |                   |         |          |
| Radiator                     | ✓         |      |                   |         |          |
| Engine Oil                   | ✓         |      |                   |         |          |
| 3- OPERATOR CAB              |           |      |                   |         |          |
|                              | Condition |      | Corrective Action |         | Comments |
|                              | Pass      | Fail | Repair            | Replace |          |
| Seat                         | ✓         |      |                   |         |          |
| Seat Belt & Mounting         | ✓         |      |                   |         |          |
| Horn, backup alarm, lights   | ✓         |      |                   |         |          |
| Controls, gauge lenses       | ✓         |      |                   |         |          |
| Mechanical connections       | ✓         |      |                   |         |          |
| Hydraulic hoses and fittings | ✓         |      |                   |         |          |
| Rams/ seals                  | ✓         |      |                   |         |          |



## CERTIFICATE OF THOROUGH EXAMINATION

This This report complies with Provision and use of work equipment regulations

RAS-Y-260630123

Certificate Page: 3 Of 3

