

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

Certificate Page: 1 Of 3

Date of Through Examination: 16/07/2026	Date of Report: 16/07/2026	Report Number: RAS-AM-260730026
---	----------------------------	--

<u>Description and identification of the equipment:</u> Vacuum Truck, Diesel powered, Hydraulic Operated	Manufacturer: ACTROS Year of Manufacture: 2017 Model: 963-0-C Serial Number: WDB96302010119962 Chassis Number: WDB96302010119962 Plate Number: 22H 23042		
<u>Name and address of employer for whom the thorough examination was made:</u> RAS AL-KHAIMA COMPANY <u>Address of premises at which the examination was made:</u> RAS AL-KHAIMA COMPANY-YARD	Tank Capacity: 24000 Ltr	Weight: 21.5 Ton	

Standard: BS 474-1:2022

Is this the first examination after installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out?				
					Within an interval of 6 months?	YES		NO	✓
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES	✓	NO	
					In accordance with an examination scheme?	YES		NO	✓
					After the occurrence of exceptional circumstances?	YES		NO	✓
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE									
Is the above a defect which is of immediate danger to persons						YES		NO	✓
Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) NONE						Yes by:			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: NONE									
Particulars of any test carried out as part of examination: The equipment has been visual and function Tested to BS 474-1:2022 & Found Satisfactory at the Time of Inspection.									
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	✓	NO		
Name & Qualifications of person making this report: Ahmed Yahya			Name of person authenticating this report: Signature: Mustafa Salman			Latest date by which next thorough examination must be carried out: 15/07/2027			
Name and address of employer of person making and authenticating this report: Hussein Ali Hussein, Basra, Burjesia									



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

RAS-AM-260730026

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Axle System	✓				
Tires and Wheels	✓				
Steering System	✓				
Brake System	✓				
Chassis Condition	✓				
Tailgate	✓				
Electrical System	✓				
Tank Condition	✓				
Reverse Alarm	✓				
Signal Light	✓				
Wind Shield	✓				
Glasses & Mirrors	✓				
Transmission	✓				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	✓				
Engine Coolant	✓				
Engine Pre-cleaner	✓				
Air Filter	✓				
All Hoses	✓				
Radiator	✓				
Engine Oil	✓				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	✓				
Seat Belt & Mounting	✓				
Horn, backup alarm, lights	✓				
Controls, gauge lenses	✓				
Mechanical connections	✓				
Hydraulic hoses and fittings	✓				
Rams/ seals	✓				



CERTIFICATE OF THOROUGH EXAMINATION

This This report complies with Provision and use of work equipment regulations

RAS-AM-260730026

Certificate Page: 3 Of 3



Mercedes-Benz		DAIMLER AG	
TYP 963-0-C	- m ³	e1*2007/46*0732	
ID 1,00 %			
BHA= 2,533			
Fahrzeugkennzeichnungsnummer	VIN	WDB96302010119962	
Vehicle Identification Number			
Zulässiges Gesamtgewicht		26000	kg
Permissible total weight			
Zulässiges Zug-Gesamtgewicht		44000	kg
Permissible combination weight			
Zulässige Achslast, Achse 1	1-	8000	kg
Permissible axle load, axle 1			
Zulässige Achslast, Achse 2	2-	11500	kg
Permissible axle load, axle 2			
Zulässige Achslast, Achse 3	3-	7500	kg
Permissible axle load, axle 3			
Zulässige Achslast, Achse 4	4-	XXXXX	kg
Permissible axle load, axle 4			
Zulässige Last der Achsgruppe	T-	19000	kg
Permissible load on axle group			

