

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

Certificate Page: 1 Of 3

Date of Through Examination: 19/07/2026	Date of Report: 19/07/2026	Report Number: RAS-AM-260730033
---	----------------------------	--

<u>Description and identification of the equipment:</u> Water Tanker Truck fitted with Water Jet, Diesel powered, Hydraulic Operated	Manufacturer: SCANIA SWEDEN Year of Manufacture: 2012 Model: CR19 Serial Number: 9090582 Chassis Number: VLUR4X20009090582 Plate Number: F 10243 Basra	
<u>Name and address of employer for whom the thorough examination was made:</u> ABRAJ AL-BADER	Capacity: 17000 Ltr	Weight: 20100 Kg
<u>Address of premises at which the examination was made:</u> RAS-YARD		

Standard: BS 474-1:2022

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	YES	NO
			Within an interval of 6 months?	
			Within an interval of 12 months?	
If the answer to the above question is YES, has the equipment been installed correctly?	YES	NO	In accordance with an examination scheme?	
			After the occurrence of exceptional circumstances?	

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons

YES NO

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**

Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

The equipment has been visual and function Tested to **BS 474-1:2022** & Found Satisfactory at the Time of Inspection.

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Name & Qualifications of person making this report: Ahmed Yahya	Name of person authenticating this report: Signature: Mustafa Salman	Latest date by which next thorough examination must be carried out: 18/07/2027
---	--	--

Name and address of employer of person making and authenticating this report:

Hussein Ali Hussein, Basra, Burjesia



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

RAS-AM-260730033

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Axle System	✓				
Tires and Wheels	✓				
Steering System	✓				
Brake System	✓				
Chassis Condition	✓				
Tailgate	✓				
Electrical System	✓				
Tank Condition	✓				
Reverse Alarm	✓				
Signal Light	✓				
Wind Shield	✓				
Glasses & Mirrors	✓				
Transmission	✓				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	✓				
Engine Coolant	✓				
Engine Pre-cleaner	✓				
Air Filter	✓				
All Hoses	✓				
Radiator	✓				
Engine Oil	✓				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	✓				
Seat Belt & Mounting	✓				
Horn, backup alarm, lights	✓				
Controls, gauge lenses	✓				
Mechanical connections	✓				
Hydraulic hoses and fittings	✓				
Rams/ seals	✓				



CERTIFICATE OF THOROUGH EXAMINATION

This This report complies with Provision and use of work equipment regulations

RAS-AM-260730033

Certificate Page: 3 Of 3

