

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Certificate Page: 1 Of 3

Date of Thorough Examination: 12/07/2026	Date of Report: 12/07/2026	Report Number: RAS-U-2607301382
--	----------------------------	--

<u>Description and identification of the equipment:</u> Man Lift Basket, Diesel powered, Hydraulic Operated	<u>Manufacturer:</u> HYUNDAI <u>Year of Manufacture:</u> 2017 <u>Model:</u> GH-290 <u>Serial Number:</u> KMFHA17GPHC017940 <u>Chassis Number:</u> KMFHA17GPHC017940 <u>Plate Number:</u> 14 B85782 KARBALA		
<u>Name and address of employer for whom the thorough examination was made:</u> ALI Al-Akbar <u>Address of premises at which the examination was made:</u> RAS \YARD	<u>Basket Manufacture:</u> KOREEL HOSE <u>Year of Manufacture:</u> 195 <u>Model:</u> RH-622-4HB-R <u>Serial Number:</u> NB130-04	<u>Working Height:</u> 30 m <u>Horizontal Reach:</u> 11.0 m <u>Safe Working Load (SWL):</u> 250 Kg	

Is this the first examination after installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out?	Within an interval of 6 months?	YES	✓	NO	
						Within an interval of 12 months?	YES		NO	✓
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES		NO	✓	
					After the occurrence of exceptional circumstances?	YES		NO	✓	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE										
Is the above a defect which is of immediate danger to persons							YES		NO	✓
Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) NONE							Yes by:			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: NONE										
Particulars of any test carried out as part of examination: The Referenced Equipment Has Been Function Tested As per EN 280-1:2022 and Found Satisfactory at the Time of Inspection.										
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	✓	NO		
Name & Qualifications of person making this report: Mustafa Saiman			Name of person authenticating this report: Signature: Ahmed Yahya			Latest date by which next thorough examination must be carried out: 11/07/2027				
Name and address of employer of person making and authenticating this report: Hussein Ali Hussein, Basra, Burjesia										

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report Number: RAS-U-2607301382

Certificate Page: 2 Of 3

GENERAL DESCRIPTION OF THE EQUIPMENT	Status			
	OK	NO	NA	Comments
Axle System	✓			
Tires and Wheels	✓			
Steering System	✓			
First Aid Kit	✓			
Brake System	✓			
Chassis Condition	✓			
Electrical System	✓			
Lifting Arm Jack	✓			
Reverse Alarm	✓			
Signal Light	✓			
Wind Shield	✓			
Glasses & Mirrors	✓			
Transmission	✓			
Operational Control	✓			
Cabin Condition	✓			
Fire Extinguisher	✓			
Leaks	✓			
Cracks	✓			
Pressure Reading	✓			
Control Operation	✓			
Standing Legs	✓			
Sand Pads	✓			
Harness Anchorage Points (Fitting & Condition)	✓			
Over Load Warning System	✓			
Emergency Lowering System	✓			
Emergency Stop Button	✓			
Boom Condition	✓			
Spark Arrester	✓			
Fuel Tank	✓			
Alarm Light	✓			
Engine Oil	✓			
Engine Coolant	✓			
Engine Pre-cleaner	✓			
Air Filter	✓			
All Hoses	✓			
Name & Qualifications of person making this report: Mustafa Mohammed				

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report Number: RAS-U-2607301382

Certificate Page: 3 Of 3

	OK	NO	NA	Comments
Radiator	✓			
Seat	✓			
Seat Belt	✓			
Mounting	✓			
Horn	✓			
Backup Alarm	✓			
Lights	✓			
Controls	✓			
Gauge lenses	✓			
Mechanical connections	✓			
Hydraulic hoses	✓			
Fittings	✓			
Rams	✓			
Seals	✓			
Level Gauge	✓			

