

Document Title

CERTIFICATE OF THOROUGH EXAMINATION

This CERTIFICATE complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Document Number: IMS-INS-LG-001	Document Type: Form	Issue Date: 11/12/2022	Revision Number: 01	Revision Date: 02/01/2024
Prepared By:	Inspection Department	Approved By:	Inspection Manager	Document Status: Controlled Document

NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE:	SAMA AL-TARIQ CO. (BERJESSIA – BASRA-IRAQ)		
ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE:	RAC YARD	CERTIFICATE NUMBER:	RAS-Y-26075006
DATE OF THOROUGH EXAMINATION	15.July.2026	DATE OF CERTIFICATE:	15.July.2026

APPLIED INSPECTION ACCORDING TO:

APPLIED STANDARD EN 361:2002 / EN 355:2002

DESCRIPTION AND IDENTIFICATION OF THE EQUIPMENT:

QTY	Serial/ID No	Item(s) Description:	
1	001	PERSONAL FALL PROTECTION EQUIPMENT (ENERGY ABSORBER) Manufacturer: Liftex Model: LX200 Maximum Allowable Length (Energy Absorber + Lanyard): 2.0 m	

Safe Working Load	150 KG	Date of manufacture if known:	N/A
Last load test Date:	N/A	Date of last thorough examination:	Unknown

OBSERVATIONS / ADDITIONAL COMMENTS RELATIVE TO THIS THOROUGH EXAMINATION

The item above inspected and found free visible defect at the time of the inspection

Question	YES	NO	Question	YES	NO	Question	YES	NO
Is this the first examination after installation or assembly at a new site or location?	☐	☒	Was the examination carried out within an interval of 6 months?	☒	☐	Was the examination carried out in accordance with an examination scheme?	☐	☒
If YES, has the equipment been installed correctly?	☐	☐	Was the examination carried out within an interval of 12 months?	☐	☒	Was the examination carried out after the occurrence of exceptional circumstances?	☐	☒

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**


Is the above an existing or imminent danger to persons *Note-This is a reportable defect ☐ YES ☒ NO

Is the above a defect which is not yet but could become a danger to persons: By: -- ☐ YES ☒ NO

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Particulars of any tests carried out as part of the examination: Thorough Examination and NDT

IS THIS EQUIPMENT SAFE TO OPERATE? ☒ YES ☐ NO

NAME & QUALIFICATIONS OF PERSON MAKING THIS CERTIFICATE:	NAME OF PERSON SIGNING OR AUTHENTICATING THIS CERTIFICATE ON BEHALF OF THE AUTHOR:	LATEST DATE BY WHICH NEXT THOROUGH EXAMINATION MUST BE CARRIED OUT:	
Name: Mustafa Salman SIGNATURE:  QUALIFICATIONS: • LEEA Lifting Accessories (LAC) Diploma • NDT Inspector – VT, MT, PT, UT	Name: Ahmed Yahya Signature: 	14.Dec.2026	
Name and address of employer of persons making and authenticating this CERTIFICATE: Emad Seif / Basra - Iraq			