

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Date of Thorough Examination: 28/07/2026		Report Date: 28/07/2026		Report number: RAS-AM-260750063																													
Name and Address of employer for whom the thorough examination was made: TAAM COMPANY			Address of premises at which the examination was made: TAAM CAMP																														
Description and identification of the equipment: Lever Hoist		Capacity: 6 Ton Length: 3 m	Safety Factor: 4:1 Size: 10 mm	Manufacture: TOYO																													
Is this the first examination after installation or assembly at a new site or location? If the answer to the above question is YES has the equipment been installed correctly?		<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td></td> </tr> </table>		YES		NO	✓	YES		NO		Was the examination carried out? <table border="1"> <tr> <td>Within an interval of 6 months?</td> <td>YES</td> <td>✓</td> <td>NO</td> <td></td> </tr> <tr> <td>Within an interval of 12 months?</td> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> <tr> <td>In accordance with an examination scheme?</td> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> <tr> <td>After the occurrence of exceptional circumstances?</td> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> </table>		Within an interval of 6 months?	YES	✓	NO		Within an interval of 12 months?	YES		NO	✓	In accordance with an examination scheme?	YES		NO	✓	After the occurrence of exceptional circumstances?	YES		NO	✓
YES		NO	✓																														
YES		NO																															
Within an interval of 6 months?	YES	✓	NO																														
Within an interval of 12 months?	YES		NO	✓																													
In accordance with an examination scheme?	YES		NO	✓																													
After the occurrence of exceptional circumstances?	YES		NO	✓																													
Serial Number: (333)			Quantity: 01	Inspection Method: VT & Dimension Check																													
Is the above a defect which is of immediate danger to persons				YES	NO ✓																												
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when) NONE			YES by:																														
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE																																	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) NONE																																	
Particulars of any tests carried out as part of the examination: (If none state NONE) The mentioned Chain Blocks have been visually examined according to BS EN13157:2009																																	
IS THIS EQUIPMENT FIT FOR PURPOSE?				YES	NO ✓																												
Name & Qualifications of person making this report: Mustafa Salman		Name of person authenticating this report: Signature: Ahmed Yanya		Latest date by which next thorough examination must be carried out: 27/01/2027																													
Name and address of employer of persons making and authenticating this report: Hussein Ali Hussein, Basra, Burjesia																																	

