

CERTIFICATE OF THOROUGH EXAMINATION

This Report Complies with the Lifting Operation and Lifting Equipment Regulations

Date of Thorough Examination: 11/07/2026		Date of Report: 11/07/2026		Report number: RAS-Y-260750435															
Name and Address of employer for whom the thorough examination was made: TAAM ENGINEERING			Address of premises at which the examination was made: TAAM YARD																
Description and identification of the equipment: Flat Webbing Sling	Safety Factor (SF): (7:1)	-Length: 4 m	WLL(s): 3 Ton	Manufacture: KINGROY Material: Polyester															
Is this the first examination after installation or assembly at a new site or location?			Was the examination carried out?																
<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> </table>			YES		NO	✓	<table border="1"> <tr> <td>Within an interval of 6 months?</td> <td>YES</td> <td>✓</td> <td>NO</td> <td></td> </tr> <tr> <td>Within an interval of 12 months?</td> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> </table>			Within an interval of 6 months?	YES	✓	NO		Within an interval of 12 months?	YES		NO	✓
YES		NO	✓																
Within an interval of 6 months?	YES	✓	NO																
Within an interval of 12 months?	YES		NO	✓															
If the answer to the above question is YES has the equipment been installed correctly?			In accordance with an examination scheme?																
<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td></td> </tr> </table>			YES		NO		<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> </table>			YES		NO	✓						
YES		NO																	
YES		NO	✓																
After the occurrence of exceptional circumstances?			<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> </table>			YES		NO	✓										
YES		NO	✓																
Serial Number: B54400037,B54400273,B54400118,B54400343,B54400281,B54400320,B54400360 B54400124,B54400165,B54400321,B54400338,B54400064,B54400056,B54400070 B54400029,B54400318,B54400086,B54400018,B54400073,B54400079,B54400075 B54400168,B54400041,B54400252,B54400083,B54400066,B54400232,B54400039 B54400030,B54400319,B54400286,B54400019,B54400063,B54400309,B54400057 B54400297,B54400166,B54400115,B54400236,B54400133,B54400238,B54400140 B54400234,B54400220,B54400278,B54400170,B54400111,B54400284,B54400275 B54400001,B54400003,B54400004			Quantity: 52	Inspection Method: VT & Dimension Check															
Is the above a defect which is of immediate danger to persons			<table border="1"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> </table>			YES		NO	✓										
YES		NO	✓																
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when) NONE			YES by:																
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE																			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) NONE																			
Particulars of any tests carried out as part of the examination: (If none state NONE) The mentioned slings have been visually examined according to BS EN 1492-1:2000+A1:2008																			
IS THIS EQUIPMENT FIT FOR PURPOSE?				<table border="1"> <tr> <td>YES</td> <td>✓</td> <td>NO</td> <td></td> </tr> </table>		YES	✓	NO											
YES	✓	NO																	
Name & Qualifications of person making this report: Mustafa Salman		Name of person authenticating this report: Signature: Ahmed Yahya		Latest date by which next thorough examination must be carried out: 10/01/2027															
Name and address of employer of persons making and authenticating this report: Hussein Ali Hussein, Basra, Burjesia																			

