

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

Certificate Page: 1 Of 3

Date of Through Examination: 22/08/2026	Date of Report: 22/08/2026	Report Number: RAS-AM-260830062
---	----------------------------	--

Description and identification of the equipment: Vacuum Truck, Diesel powered, Hydraulic Operated	Manufacturer: SCANIA Year of Manufacture: 2011 Model: G 360 B4x2NB Serial Number: 5543285 Chassis Number: YS2G4X20005543285 Plate Number: 22 L12551	
Name and address of employer for whom the thorough examination was made: FAJR AL RUMILA COMPANY Address of premises at which the examination was made: FAJR AL RUMILA CAMP	Tank Capacity: 20,000 Ltr Combination Weight: 40,000 Kg	

Standard: BS 474-1:2022

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	YES	NO
			Within an interval of 6 months?	
			Within an interval of 12 months?	
If the answer to the above question is YES, has the equipment been installed correctly?	YES	NO	In accordance with an examination scheme?	
			After the occurrence of exceptional circumstances?	

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons

YES NO

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**

Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

The equipment has been visual and function Tested to **BS 474-1:2022** & Found Satisfactory at the Time of Inspection.

IS THIS EQUIPMENT SAFE TO OPERATE?

YES NO

Name & Qualifications of person making this report:
Ahmed Yahya

Name of person authenticating this report:
Signature: **Mustafa Salman**

Latest date by which next thorough examination must be carried out:
21/08/2027

Name and address of employer of person making and authenticating this report:

Hussein Ali Hussein, Basra, Burjesia



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

RAS-AM-260830062

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Axle System	✓				
Tires and Wheels	✓				
Steering System	✓				
Brake System	✓				
Chassis Condition	✓				
Tailgate	✓				
Electrical System	✓				
Tank Condition	✓				
Reverse Alarm	✓				
Signal Light	✓				
Wind Shield	✓				
Glasses & Mirrors	✓				
Transmission	✓				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	✓				
Engine Coolant	✓				
Engine Pre-cleaner	✓				
Air Filter	✓				
All Hoses	✓				
Radiator	✓				
Engine Oil	✓				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	✓				
Seat Belt & Mounting	✓				
Horn, backup alarm, lights	✓				
Controls, gauge lenses	✓				
Mechanical connections	✓				
Hydraulic hoses and fittings	✓				
Rams/ seals	✓				



CERTIFICATE OF THOROUGH EXAMINATION

This This report complies with Provision and use of work equipment regulations

Certificate Page: 3 Of 3

RAS-AM-260830062



2025452

SCANIA		e4*2007/46*1128			
VIN		YS2G4X20005543285		Cab Type	
Regist for	(DE)	Technically permissible		Serial No.	
Total	18000	Kg	19000	Kg	Approval
Combination	40000	Kg	50000	Kg	Cab Colour
Axle 1	7500	Kg	7500	Kg	Ch No.
Axle 2	11500	Kg	11500	Kg	Ch Colour
Axle 3	X	Kg	X	Kg	ADR GTW
Axle 4	X	Kg	X	Kg	Ch Type
Axle 5	X	Kg	X	Kg	Produced in
Axle 6	X	Kg	X	Kg	

CG20N
5543285
E4-29R-030115
1366386
5543285
1346692
X
G 360 B4x2NB
THE NETHERLANDS

