

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

Certificate Page: 1 Of 3

Date of Through Examination: 25/08/2026	Date of Report: 25/08/2026	Report Number: RAS-AM-260830066
---	----------------------------	--

<u>Description and identification of the equipment:</u> Water Tanker Truck fitted with Water Jet, Diesel powered, Hydraulic Operated	Manufacturer: SCANIA SWEDEN Year of Manufacture: 2008 Model: CR19 Serial Number: YS2R6X20001262861 Chassis Number: YS2R6X20001262861 Plate Number: 14 A13038	
<u>Name and address of employer for whom the thorough examination was made:</u> ABRAJ AL-BADER	Capacity: 20,000 Ltr	Weight: 27,000 Kg
<u>Address of premises at which the examination was made:</u> AL-ZUBAIR		

Standard: BS 474-1:2022

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	✓
If the answer to the above question is YES, has the equipment been installed correctly?				
	YES		NO	✓

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons

YES NO ✓

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**

Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

The equipment has been visual and function Tested to **BS 474-1:2022** & Found Satisfactory at the Time of Inspection.

IS THIS EQUIPMENT SAFE TO OPERATE? YES ✓ NO

Name & Qualifications of person making this report:
Ahmed Yahya

Name of person authenticating this report:
Signature: **Mustafa Salman**

Latest date by which next thorough examination must be carried out:
24/08/2027

Name and address of employer of person making and authenticating this report:
Hussein Ali Hussein, Basra, Burjesia



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

RAS-AM-260830066

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Axle System	✓				
Tires and Wheels	✓				
Steering System	✓				
Brake System	✓				
Chassis Condition	✓				
Tailgate	✓				
Electrical System	✓				
Tank Condition	✓				
Reverse Alarm	✓				
Signal Light	✓				
Wind Shield	✓				
Glasses & Mirrors	✓				
Transmission	✓				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	✓				
Engine Coolant	✓				
Engine Pre-cleaner	✓				
Air Filter	✓				
All Hoses	✓				
Radiator	✓				
Engine Oil	✓				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	✓				
Seat Belt & Mounting	✓				
Horn, backup alarm, lights	✓				
Controls, gauge lenses	✓				
Mechanical connections	✓				
Hydraulic hoses and fittings	✓				
Rams/ seals	✓				



CERTIFICATE OF THOROUGH EXAMINATION

This This report complies with Provision and use of work equipment regulations

RAS-AM-260830066

Certificate Page: 3 Of 3



SCANIA SWEDEN		MASS		MASS	
		Maximum legal	Technically permissible	kg	kg
YB286X200#CE2861		x	x	kg	
Cab type	3219	1	x	kg	
Serial No	7191192	2	x	kg	
Approval	E 021 CH	3	x	kg	
Cab col	1396386	4	x	kg	

