

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

Certificate Page: 1 Of 3

Date of Through Examination: 25/07/2026	Date of Report: 25/07/2026	Report Number: RAS-Y-26083009
---	----------------------------	-------------------------------

<u>Description and identification of the equipment:</u> Dump Truck, Diesel powered, Hydraulic Operated	<u>Manufacturer:</u> SCANIA <u>Year of Manufacture:</u> 2012 <u>Model:</u> CR19 <u>Serial Number:</u> 1201232 <u>Chassis Number:</u> YS2RE8X4Z01201232 <u>Plate Number:</u> T 61162		
<u>Name and address of employer for whom the thorough examination was made:</u> Al-Yamama Company <u>Address of premises at which the examination was made:</u> OM-QASR	<u>Cubic Capacity:</u> 15 m ³	<u>Weight:</u> 26,000 kg	

Standard: BS 474-1:2022

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	YES	NO
	☒	☐	Within an interval of 6 months?	☒
	☐	☐	Within an interval of 12 months?	☒
If the answer to the above question is YES, has the equipment been installed correctly?	☒	☐	In accordance with an examination scheme?	☒
	☐	☐	After the occurrence of exceptional circumstances?	☒

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons	YES	NO
Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) NONE	Yes by:	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:
The equipment has been visual and function Tested to **BS 474-1:2022** & Found Satisfactory at the Time of Inspection.

IS THIS EQUIPMENT SAFE TO OPERATE? YES ☒ NO ☐

Name & Qualifications of person making this report: Ahmed Yahya	Name of person authenticating this report: Signature: Mustafa Salman	Latest date by which next thorough examination must be carried out: 24/07/2027
---	--	--

Name and address of employer of person making and authenticating this report:
Hussein Ali Hussein, Basra, Burjesia



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

RAS-Y-26083009

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Axle System	✓				
Tires and Wheels	✓				
Steering System	✓				
Brake System	✓				
Chassis Condition	✓				
Tailgate	✓				
Electrical System	✓				
Main Jack	✓				
Reverse Alarm	✓				
Signal Light	✓				
Wind Shield	✓				
Glasses & Mirrors	✓				
Transmission	✓				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	✓				
Engine Coolant	✓				
Engine Pre-cleaner	✓				
Air Filter	✓				
All Hoses	✓				
Radiator	✓				
Engine Oil	✓				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	✓				
Seat Belt & Mounting	✓				
Horn, backup alarm, lights	✓				
Controls, gauge lenses	✓				
Mechanical connections	✓				
Hydraulic hoses and fittings	✓				
Rams/ seals	✓				



CERTIFICATE OF THOROUGH EXAMINATION

This This report complies with Provision and use of work equipment regulations

RAS-Y-26083009

Certificate Page: 3 Of 3



SCANIA				Technically permissible		Cab type	
YS2RE8X4Z01201232						CR19	
Total	26000	Kg		26100	Kg	Serial no	1201232
Combination	60000	Kg		60000	Kg	Approval	T 072 Fh
Axle 1-	X	Kg		7500	Kg	Cab col	1396114
Axle 2-	X	Kg		11500	Kg	Ch No	1201232
Axle 3-	X	Kg		7100	Kg	Ch colour	1346692
Axle 4-	X	Kg		X	Kg	ADR GTW	X
Axle 5-	X	Kg		X	Kg	Ch type	R 500 LB8X4MNB
5 th wheel	X	Kg		X	Kg		

