

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

Certificate Page: 1 Of 3

Date of Through Examination: 22/08/2026	Date of Report: 22/08/2026	Report Number: RAS-Y-26083043
---	----------------------------	-------------------------------

<u>Description and identification of the equipment:</u> Trailer Truck, Diesel powered, Hydraulic Operated	Manufacturer: MERCEDES Year of Manufacture: 2021 Model: 963-4-A Serial Number: W1T96340310474374 Chassis Number: W1T96340310474374 Plate Number: 22 B 39208	
<u>Name and address of employer for whom the thorough examination was made:</u> BMC Company <u>Address of premises at which the examination was made:</u> BMC YARD	Weight: 44,000 kg	

Standard: BS 474-1:2022

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	YES	NO
			Within an interval of 6 months?	
			Within an interval of 12 months?	
If the answer to the above question is YES, has the equipment been installed correctly?	YES	NO	In accordance with an examination scheme?	
			After the occurrence of exceptional circumstances?	

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons	YES	NO
Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) NONE	Yes by:	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:
The equipment has been visual and function Tested to **BS 474-1:2022** & Found Satisfactory at the Time of Inspection.

IS THIS EQUIPMENT SAFE TO OPERATE? YES ☒ NO ☐

Name & Qualifications of person making this report: Ahmed Yahya	Name of person authenticating this report: Signature: Mustafa Salman	Latest date by which next thorough examination must be carried out: 21/08/2027
---	--	--

Name and address of employer of person making and authenticating this report:
Hussein Ali Hussein, Basra, Burjesia



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

RAS-Y-26083043

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Axle System	✓				
Tires and Wheels	✓				
Steering System	✓				
Brake System	✓				
Chassis Condition	✓				
Tailgate	✓				
Electrical System	✓				
Main Jack	✓				
Reverse Alarm	✓				
Signal Light	✓				
Wind Shield	✓				
Glasses & Mirrors	✓				
Transmission	✓				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	✓				
Engine Coolant	✓				
Engine Pre-cleaner	✓				
Air Filter	✓				
All Hoses	✓				
Radiator	✓				
Engine Oil	✓				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	✓				
Seat Belt & Mounting	✓				
Horn, backup alarm, lights	✓				
Controls, gauge lenses	✓				
Mechanical connections	✓				
Hydraulic hoses and fittings	✓				
Rams/ seals	✓				



CERTIFICATE OF THOROUGH EXAMINATION

This This report complies with Provision and use of work equipment regulations

RAS-Y-26083043

Certificate Page: 3 Of 3



Mercedes-Benz		Daimler Truck AG	
TYP 963-4-A			
ED 1,00 %			
IHA- 2,733			
Fahrzeugidentifizierungsnummer	VIN	W1T96340310474374	
Technisch zulässiges Gesamtgewicht	Technically permissible total weight	18000	kg
Technisch zulässiges Zug-Gesamtgewicht	Technically permissible combination weight	44000	kg
Technisch zulässige Achslast, Achse 1	Technically permissible axle load, axle 1	7500	kg
Technisch zulässige Achslast, Achse 2	Technically permissible axle load, axle 2	11500	kg
Technisch zulässige Achslast, Achse 3	Technically permissible axle load, axle 3	XXXXX	kg
Technisch zulässige Achslast, Achse 4	Technically permissible axle load, axle 4	XXXXX	kg
Technisch zulässige Last der Achsgruppe	Technically permissible load on axle group	XXXXX	kg

