

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

Certificate Page: 1 Of 3

Date of Through Examination: 22/08/2026	Date of Report: 22/08/2026	Report Number: RAS-Y-26083048
---	----------------------------	-------------------------------

Description and identification of the equipment: Fuel Tanker Truck fitted with Water Jet, Diesel powered, Hydraulic Operated	Manufacturer: SCANIA Year of Manufacture: 2009 Model: CR19 Serial Number: XLER6X20005214822 Chassis Number: XLER6X20005214822 Plate Number: 22 H12908	
Name and address of employer for whom the thorough examination was made: BMC Company Address of premises at which the examination was made: BMC YARD	Capacity: 21000 Ltr Weight: 26500 Kg	

Standard: BS 474-1:2022

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	YES	NO
			Within an interval of 6 months?	
			Within an interval of 12 months?	
If the answer to the above question is YES, has the equipment been installed correctly?	YES	NO	In accordance with an examination scheme?	
			After the occurrence of exceptional circumstances?	

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons

YES NO

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**

Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

The equipment has been visual and function Tested to **BS 474-1:2022** & Found Satisfactory at the Time of Inspection.

IS THIS EQUIPMENT SAFE TO OPERATE?

YES NO

Name & Qualifications of person making this report:
Ahmed Yahya

Name of person authenticating this report:
Signature: **Mustafa Salman**

Latest date by which next thorough examination must be carried out:
21/08/2027

Name and address of employer of person making and authenticating this report:

Hussein Ali Hussein, Basra, Burjesia



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

RAS-Y-26083048

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Axle System	✓				
Tires and Wheels	✓				
Steering System	✓				
Brake System	✓				
Chassis Condition	✓				
Tailgate	✓				
Electrical System	✓				
Tank Condition	✓				
Reverse Alarm	✓				
Signal Light	✓				
Wind Shield	✓				
Glasses & Mirrors	✓				
Transmission	✓				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	✓				
Engine Coolant	✓				
Engine Pre-cleaner	✓				
Air Filter	✓				
All Hoses	✓				
Radiator	✓				
Engine Oil	✓				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	✓				
Seat Belt & Mounting	✓				
Horn, backup alarm, lights	✓				
Controls, gauge lenses	✓				
Mechanical connections	✓				
Hydraulic hoses and fittings	✓				
Rams/ seals	✓				



CERTIFICATE OF THOROUGH EXAMINATION

This This report complies with Provision and use of work equipment regulations

RAS-Y-26083048

Certificate Page: 3 Of 3



SCANIA			
XLER6X2000-5214822		Technically permissible	Cab type CR19
Total	26500 Kg	26500 Kg	Serial no 5214822
Combination	50000 Kg	50000 Kg	Approval T 071 Fh
Axle 1-	7500 Kg	7500 Kg	Cab col 1366386
Axle 2-	1500 Kg	1500 Kg	Ch No 5214822
Axle 3-	1500 Kg	1500 Kg	Ch colour 1366692
Axle 4-	X Kg	X Kg	ADR GTW
Axle 5-	X Kg	X Kg	Ch type R 380 / 8612F
6 th wheel	X Kg	X Kg	

