

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

Certificate Page: 1 Of 3

Date of Through Examination: 20/08/2026	Date of Report: 20/08/2026	Report Number: RAS-U-26083082
---	----------------------------	-------------------------------

Description and identification of the equipment: Dump Truck, Diesel powered, Hydraulic Operated	Manufacturer: SCANIA Year of Manufacture: 2007 Model: CR19 Serial Number: XLER4X20005161494 Chassis Number: XLER4X20005161494 Plate Number: 44613 Basra	
Name and address of employer for whom the thorough examination was made: FAJR AL-RUMALIA Company Address of premises at which the examination was made: AL-ZUBAR	Cubic Capacity: 15 m ³ Weight: 26,000 kg	

Standard: BS 474-1:2022

Is this the first examination after installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out?				
					Within an interval of 6 months?	YES		NO	✓
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES	✓	NO	
					In accordance with an examination scheme?	YES		NO	✓
					After the occurrence of exceptional circumstances?	YES		NO	✓
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE									
Is the above a defect which is of immediate danger to persons						YES		NO	✓
Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) NONE						Yes by:			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: NONE									
Particulars of any test carried out as part of examination: The equipment has been visual and function Tested to BS 474-1:2022 & Found Satisfactory at the Time of Inspection.									
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	✓	NO		
Name & Qualifications of person making this report: Ahmed Yahya			Name of person authenticating this report: Signature: Mustafa Salman			Latest date by which next thorough examination must be carried out: 20/08/2027			
Name and address of employer of person making and authenticating this report: Hussein Ali Hussein, Basra, Burjesia									



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

RAS-U-26083082

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Axle System	✓				
Tires and Wheels	✓				
Steering System	✓				
Brake System	✓				
Chassis Condition	✓				
Tailgate	✓				
Electrical System	✓				
Main Jack	✓				
Reverse Alarm	✓				
Signal Light	✓				
Wind Shield	✓				
Glasses & Mirrors	✓				
Transmission	✓				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	✓				
Engine Coolant	✓				
Engine Pre-cleaner	✓				
Air Filter	✓				
All Hoses	✓				
Radiator	✓				
Engine Oil	✓				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	✓				
Seat Belt & Mounting	✓				
Horn, backup alarm, lights	✓				
Controls, gauge lenses	✓				
Mechanical connections	✓				
Hydraulic hoses and fittings	✓				
Rams/ seals	✓				



CERTIFICATE OF THOROUGH EXAMINATION

This This report complies with Provision and use of work equipment regulations

RAS-U-26083082

Certificate Page: 3 Of 3



SCANIA				Technically permissible				Cab type			
XLER4X20005161494								CR19			
Total	18200	Kg		18200	Kg			Serial no	5161494		
Combination	50000	Kg		50000	Kg			Approval	T 071-Fh		
Axle 1-	6700	Kg		6700	Kg			Cab col	1366386		
Axle 2-	11500	Kg		11500	Kg			Ch. No	5161494		
Axle 3-	X	Kg		X	Kg			Ch. colour	1346632		
Axle 4-	X	Kg		X	Kg			ADR GTW	X		
Axle 5-	X	Kg		X	Kg			Ch. type	R 380 LA4X2MNA		
5-th wheel	X	Kg		X	Kg						

