

CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

Certificate Page: 1 Of 3

Date of Through Examination: 08/08/2026	Date of Report: 08/08/2026	Report Number: RAS-U- 2608309
---	----------------------------	-------------------------------

Description and identification of the equipment: Vacuum Truck, Diesel powered, Hydraulic Operated	Manufacturer: SCANIA Year of Manufacture: 2009 Model: CR19 Serial Number: XLER6X20005212227 Chassis Number: XLER6X20005212227 Plate Number: 22 A61438	
Name and address of employer for whom the thorough examination was made: Sumuo AL-Mukhayam Company Address of premises at which the examination was made: RAS Yard / Al-Burjesia	Tank Capacity: 21500 Ltr Weight: 27000 Kg	

Standard: BS 474-1:2022

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	YES	NO
			Within an interval of 6 months?	
			Within an interval of 12 months?	
If the answer to the above question is YES, has the equipment been installed correctly?	YES	NO	In accordance with an examination scheme?	
			After the occurrence of exceptional circumstances?	

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Is the above a defect which is of immediate danger to persons

YES NO

Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) **NONE**

Yes by:

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **NONE**

Particulars of any test carried out as part of examination:

The equipment has been visual and function Tested to **BS 474-1:2022** & Found Satisfactory at the Time of Inspection

IS THIS EQUIPMENT SAFE TO OPERATE?


YES NO

Name & Qualifications of person making this report: **Mohammed Kamal**

Name of person authenticating this report: Signature: **Ahmed Yahya**

Latest date by which next thorough examination must be carried out: **07/08/2027**

Name and address of employer of person making and authenticating this report:
Hussein Ali Hussein, Basra, Burjesia



CERTIFICATE OF THOROUGH EXAMINATION

This report complies with Provision and use of work equipment regulations

RAS-U-2608309

Certificate Page: 2 Of 3

1- FROM GROUND					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Axle System	✓				
Tires and Wheels	✓				
Steering System	✓				
Brake System	✓				
Chassis Condition	✓				
Tailgate	✓				
Electrical System	✓				
Tank Condition	✓				
Reverse Alarm	✓				
Signal Light	✓				
Wind Shield	✓				
Glasses & Mirrors	✓				
Transmission	✓				
2- ENGINE COMPARTMENT					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Engine Oil	✓				
Engine Coolant	✓				
Engine Pre-cleaner	✓				
Air Filter	✓				
All Hoses	✓				
Radiator	✓				
Engine Oil	✓				
3- OPERATOR CAB					
	Condition		Corrective Action		Comments
	Pass	Fail	Repair	Replace	
Seat	✓				
Seat Belt & Mounting	✓				
Horn, backup alarm, lights	✓				
Controls, gauge lenses	✓				
Mechanical connections	✓				
Hydraulic hoses and fittings	✓				
Rams/ seals	✓				

This This report complies with Provision and use of work equipment regulations

Certificate Page: 3 Of 3



SCANIA SWEDEN		MASSES		MASSES Scania design		R124 GB6X2NE 420	
		Maximum legal	Technically permissible				
X		27000	X	kg	27000	kg	
XL FR6 X2000 4456294		50000	X	kg	50000	kg	X
Cab type	CR19	1- 8000	X	kg	1- 8000	kg	Ch No 4456294
Serial No	4956294	2- 11500	X	kg	2- 11500	kg	Ch colour 1346692
Approval	T 071 FH	3- 7500	X	kg	3- 7500	kg	
Cab col	1386642	4- X	X	kg	4- X	kg	X