

THROUGH VISUAL & MAGNETIC PARTICLE INSPECTION REPORT

Certificate No: RAS-AM-260850087		Date: 09/08/2026	
Customer: HYLNDAL E&C Company		Due Date: 08/02/2027	
Location: Iraq- Basra			
Name and Address of Owner HYUNDAI / BRUP		Type Mobile -A- Frame	
Trolley Capacity: 5 Ton		Runway Beam Size: 200 mm	
Trolley S.N: 18020027		Spam: 2750 mm	
SWL: 2 Ton		Quantity: 01	
		Serial Number: (GEH-001)	
			
Inspection Result: VISUAL AND MAGNETIC PARTICLE INSPECTION (MPI) HAD BEEN DONE ON WELD & CRITICAL AREAS FOR THE ABOVE DESCRIPTION AND FOUND VISUALY: SURFACE INSPECTION OF WELDING.... (ACCEPTED) M.P.I: FREE FROM SURFACE CRACKS OR OTHER DISCONTINUITIES OF INSPECTION...(ACCEPTED)			
Inspection Method I - MPI Test, Visual Test & Load Test		Final Results PASSED	
NDT DETAILS			
Equipment Type: YOKE S/N: A12.512		Standard: ASTM E709	
Method: WET		Indicator: MAG INK	
Recommendation of Certificate			
This is to certify that the undersigned, a competent inspector, did attend the site for testing to examine and ascertain that this Mobil - A- Frame is safe for the intended use with the limits specified providing			
Name & Qualifications of person making this report: AHMED YAHYA		Name of person authenticating this report: MUSTAFA SALMAN	

