

## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

|                                          |                            |                                        |
|------------------------------------------|----------------------------|----------------------------------------|
| Date of Thorough Examination: 17/08/2026 | Date of Report: 17/08/2026 | Report number: <b>RAS-AM-260850100</b> |
|------------------------------------------|----------------------------|----------------------------------------|

|                                                                                                 |                                                                                                                                                                             |
|-------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Name and Address of employer for whom the thorough examination was made:<br><b>TAAM COMPANY</b> | Address of premises at which the examination was made:<br><b>TAAM COMPANY CAMP</b>                                                                                          |
| Description and identification of the equipment:<br><br><b>SPREADER BEAM</b>                    | <b>Self-Weight:</b> 800 kg<br><b>Dimensions:</b> 500 × 70 × 50 cm<br><b>Model:</b> K1001<br><b>Manufacture Date:</b> 2025<br><b>Manufacture:</b> KEDY<br><b>SWL:</b> 50 Ton |



**EXAMINED IN ACCORDING TO BS EN 13155:2003 + A2: 2009**

### Tools Details

| Description | S/N         | Description    | S/N | Description     | S/N        |
|-------------|-------------|----------------|-----|-----------------|------------|
| Load Cell   | 30682/25532 | Measuring Tape | N/A | Digital Caliper | 4000576010 |

### NDT Details

| Standard  | BS EN 13001-1:2015                                                                                                             | YOKE SN. | A12-512 | Contrast Media | White Contrast |
|-----------|--------------------------------------------------------------------------------------------------------------------------------|----------|---------|----------------|----------------|
| Procedure | RAS-T-21090008                                                                                                                 | Method   | Wet     | Indicator      | MAG INK        |
| Results   | MPI was carried out on Spreader Beam welding, stress points and they were found free of surface defects at time of inspection. |          |         |                |                |

|                                                                                         |     |  |    |   |                                                    |     |   |    |   |
|-----------------------------------------------------------------------------------------|-----|--|----|---|----------------------------------------------------|-----|---|----|---|
|                                                                                         |     |  |    |   |                                                    |     |   |    |   |
| Is this the first examination after installation or assembly at a new site or location? | YES |  | NO | ✓ | Was the examination carried out:                   |     |   |    |   |
|                                                                                         |     |  |    |   | Within an interval of 6 months?                    | YES | ✓ | NO |   |
| If the answer to the above question is YES has the equipment been installed correctly?  | YES |  | NO |   | Within an interval of 12 months?                   | YES |   | NO | ✓ |
|                                                                                         |     |  |    |   | In accordance with an examination scheme?          | YES |   | NO | ✓ |
|                                                                                         |     |  |    |   | After the occurrence of exceptional circumstances? | YES |   | NO | ✓ |

|                                      |                     |                                                      |
|--------------------------------------|---------------------|------------------------------------------------------|
| <b>Serial Number:</b> (K10012521501) | <b>Quantity:</b> 01 | <b>Inspection Method:</b> VT & MPI & Dimension Check |
|--------------------------------------|---------------------|------------------------------------------------------|

|                                                               |     |  |    |   |
|---------------------------------------------------------------|-----|--|----|---|
| Is the above a defect which is of immediate danger to persons | YES |  | NO | ✓ |
|---------------------------------------------------------------|-----|--|----|---|



|                                                                                                                          |         |
|--------------------------------------------------------------------------------------------------------------------------|---------|
| Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when) <b>NONE</b> | YES by: |
|--------------------------------------------------------------------------------------------------------------------------|---------|

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**


Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state **NONE**) **NONE**

Particulars of any tests carried out as part of the examination: (If none state **NONE**)  
The Referenced Equipment Has Been Visual & Load Tested As per **BS EN 13155:2003 + A2: 2009** and Found Satisfactory at the Time of Inspection.



**IS THIS EQUIPMENT FIT FOR PURPOSE?** YES ☒ NO ☐

|                                                                                                                                                           |                                                                                                                                                          |                                                                                   |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| Name & Qualifications of person making this report:<br>Mustafa Salman  | Name of person authenticating this report:<br>Signature: Ahmed Yahya  | Latest date by which next thorough examination must be carried out:<br>16/02/2027 |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|

Name and address of employer of persons making and authenticating this report:  
Hussein Ali Hussein, Basra, Burjesia



## THROUGH VISUAL & MAGNETIC PARTICLE INSPECTION REPORT

|                                                                                                                                                                          |  |                                                                                                                                                                  |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| <b>Certificate No:</b> RAS- AM-260850100                                                                                                                                 |  | <b>Date:</b> 17/AUGUST/2026                                                                                                                                      |  |
| <b>Customer:</b> TAAM COMPANY                                                                                                                                            |  | <b>Due Date:</b> 16/FEBRUARY/2027                                                                                                                                |  |
| <b>Location:</b> Iraq- Basra                                                                                                                                             |  |                                                                                                                                                                  |  |
| <b>Name and Address of Owner</b><br>TAAM COMPANY CAMP                                                                                                                    |  | <b>Type</b><br>SPREADER BEAM WELDING AND STRESS POINTS                                                                                                           |  |
| <b>Serial Number:</b><br>• (K10012521501)                                                                                                                                |  | <b>Quantity</b><br>01                                                                                                                                            |  |
|   |  |                                                                                                                                                                  |  |
| <b>Inspection Method</b><br>1 - (MPI Test) & Visual Test                                                                                                                 |  | <b>Final Results</b><br>PASSED                                                                                                                                   |  |
| <b>NDT DETAILS</b>                                                                                                                                                       |  |                                                                                                                                                                  |  |
| <b>Equipment Type:</b> YOKE S/N: A12.512                                                                                                                                 |  | <b>Standard:</b> ASTM E709                                                                                                                                       |  |
| <b>Indicator:</b> MAG INK                                                                                                                                                |  | <b>Method:</b> WET                                                                                                                                               |  |
| <b>Inspection Result:</b>                                                                                                                                                |  |                                                                                                                                                                  |  |
| VISUAL AND MAGNETIC PRATICLE INSPECTION (M.P.I) HAD BEEN DONE ON WELD, FORGN & CRITICAL AREAS FOR THE ABOVE DESCRIPTION                                                  |  |                                                                                                                                                                  |  |
| <b>AND FOUND</b>                                                                                                                                                         |  |                                                                                                                                                                  |  |
| VISUALLY: SURFACE INSPECTION OF WELDING.... (ACCEPTED)<br>M.P.I: FREE FROM SURFACE CRACKS OR ANY OTHER DISCONTINUITIES AT TIME OF INSPECTION...(ACCEPTED)                |  |                                                                                                                                                                  |  |
| <b>Name &amp; Qualifications of person making this report:</b><br>Mustafa Salman      |  | <b>Name of person authenticating this report:</b><br>Signature: Ahmed Yahya  |  |

