

## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Certificate Page: 1 Of 3

|                                         |                            |                                |
|-----------------------------------------|----------------------------|--------------------------------|
| Date of Through Examination: 02/09/2026 | Date of Report: 02/09/2026 | Report Number: RAS-MU-26093031 |
|-----------------------------------------|----------------------------|--------------------------------|

|                                                                                                                                                                                              |                                                                                                                                                                                                                       |                                                                                                                    |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| <u>Description and identification of the equipment:</u><br><br><b>Man Lift Basket, Diesel powered, Hydraulic Operated</b>                                                                    | <u>Manufacturer:</u> HINO<br><u>Year of Manufacture:</u> 2020<br><u>Model:</u> KK-XZU410M-TKFSS6<br><u>Serial Number:</u> XZU410-000404<br><u>Chassis Number:</u> XZU410-000404<br><u>Plate Number:</u> R 52536 Basra |                                                                                                                    |  |
| <u>Name and address of employer for whom the thorough examination was made:</u><br><b>ZAIN AL-AEMAL</b><br><u>Address of premises at which the examination was made:</u><br><b>AI-ZUBAIR</b> | <u>Basket Manufacture:</u> TADANO<br><u>Year of Manufacture:</u> 2003<br><u>Model:</u> AT-150S-2-30201<br><u>Serial Number:</u> HD5431                                                                                | <u>Working Height:</u><br>14.8 m<br><u>Horizontal Reach:</u><br>10.8<br><u>Safe Working Load (SWL):</u><br>1000 Kg |                                                                                     |

|                                                                                         |                                  |  |    |   |                                                    |     |   |    |
|-----------------------------------------------------------------------------------------|----------------------------------|--|----|---|----------------------------------------------------|-----|---|----|
| Is this the first examination after installation or assembly at a new site or location? | Was the examination carried out? |  |    |   |                                                    |     |   |    |
|                                                                                         | YES                              |  | NO | ✓ | Within an interval of 6 months?                    | YES | ✓ | NO |
| If the answer to the above question is YES, has the equipment been installed correctly? |                                  |  |    |   | Within an interval of 12 months?                   | YES |   | NO |
|                                                                                         | YES                              |  | NO |   | In accordance with an examination scheme?          | YES |   | NO |
|                                                                                         |                                  |  |    |   | After the occurrence of exceptional circumstances? | YES |   | NO |

|                                                                                                                                                                                                |         |  |    |   |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|--|----|---|
| Particulars of any repair, renewal or alteration required to remedy the defect identified above: <b>NONE</b>                                                                                   |         |  |    |   |
| Is the above a defect which is of immediate danger to persons                                                                                                                                  | YES     |  | NO | ✓ |
| Is the above a defect which is not yet but could become a danger to persons: (if YES state the date by when) <b>NONE</b>                                                                       | Yes by: |  |    |   |
| Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: <b>NONE</b>                                                    |         |  |    |   |
| Particulars of any test carried out as part of examination:<br>The Referenced Equipment Has Been Function Tested As per <b>EN 280-1:2022</b> and Found Satisfactory at the Time of Inspection. |         |  |    |   |

|                                                                        |  |                                                                                |  |     |                                                                                          |    |  |  |
|------------------------------------------------------------------------|--|--------------------------------------------------------------------------------|--|-----|------------------------------------------------------------------------------------------|----|--|--|
| IS THIS EQUIPMENT SAFE TO OPERATE?                                     |  |                                                                                |  | YES | ✓                                                                                        | NO |  |  |
| Name & Qualifications of person making this report: <b>AHMED YAHYA</b> |  | Name of person authenticating this report:<br>Signature: <b>Mustafa Salman</b> |  |     | Latest date by which next thorough examination must be carried out:<br><b>01/03/2027</b> |    |  |  |

|                                                                                                                              |  |  |  |  |  |  |  |  |
|------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|--|--|--|
| Name and address of employer of person making and authenticating this report:<br><b>Hussein Ali Hussein, Basra, Burjesia</b> |  |  |  |  |  |  |  |  |
|------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|--|--|--|



## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report Number: RAS-MU-26093031

Certificate Page: 2 Of 3

| GENERAL DESCRIPTION OF THE EQUIPMENT           | Status |    |    |          |
|------------------------------------------------|--------|----|----|----------|
|                                                | OK     | NO | NA | Comments |
| Axle System                                    | ✓      |    |    |          |
| Tires and Wheels                               | ✓      |    |    |          |
| Steering System                                | ✓      |    |    |          |
| First Aid Kit                                  | ✓      |    |    |          |
| Brake System                                   | ✓      |    |    |          |
| Chassis Condition                              | ✓      |    |    |          |
| Electrical System                              | ✓      |    |    |          |
| Lifting Arm Jack                               | ✓      |    |    |          |
| Reverse Alarm                                  | ✓      |    |    |          |
| Signal Light                                   | ✓      |    |    |          |
| Wind Shield                                    | ✓      |    |    |          |
| Glasses & Mirrors                              | ✓      |    |    |          |
| Transmission                                   | ✓      |    |    |          |
| Operational Control                            | ✓      |    |    |          |
| Cabin Condition                                | ✓      |    |    |          |
| Fire Extinguisher                              | ✓      |    |    |          |
| Leaks                                          | ✓      |    |    |          |
| Cracks                                         | ✓      |    |    |          |
| Pressure Reading                               | ✓      |    |    |          |
| Control Operation                              | ✓      |    |    |          |
| Standing Legs                                  | ✓      |    |    |          |
| Sand Pads                                      | ✓      |    |    |          |
| Harness Anchorage Points (Fitting & Condition) | ✓      |    |    |          |
| Over Load Warning System                       | ✓      |    |    |          |
| Emergency Lowering System                      | ✓      |    |    |          |
| Emergency Stop Button                          | ✓      |    |    |          |
| Boom Condition                                 | ✓      |    |    |          |
| Spark Arrester                                 | ✓      |    |    |          |
| Fuel Tank                                      | ✓      |    |    |          |
| Alarm Light                                    | ✓      |    |    |          |
| Engine Oil                                     | ✓      |    |    |          |
| Engine Coolant                                 | ✓      |    |    |          |
| Engine Pre-cleaner                             | ✓      |    |    |          |
| Air Filter                                     | ✓      |    |    |          |
| All Hoses                                      | ✓      |    |    |          |

Name & Qualifications of person making this report:

Ahmed Yahya



## CERTIFICATE OF THOROUGH EXAMINATION

This report complies with the Lifting Operation and Lifting Equipment Regulations

Report Number: RAS-MU-26093031

Certificate Page: 3 Of 3

|                        | OK | NO | NA | Comments |
|------------------------|----|----|----|----------|
| Radiator               | ✓  |    |    |          |
| Seat                   | ✓  |    |    |          |
| Seat Belt              | ✓  |    |    |          |
| Mounting               | ✓  |    |    |          |
| Horn                   | ✓  |    |    |          |
| Backup Alarm           | ✓  |    |    |          |
| Lights                 | ✓  |    |    |          |
| Controls               | ✓  |    |    |          |
| Gauge lenses           | ✓  |    |    |          |
| Mechanical connections | ✓  |    |    |          |
| Hydraulic hoses        | ✓  |    |    |          |
| Fittings               | ✓  |    |    |          |
| Rams                   | ✓  |    |    |          |
| Seals                  | ✓  |    |    |          |
| Level Gauge            | ✓  |    |    |          |

