RAYAT AL-SHARQ راية الشرق
For Trading, General Contracting, General Transportation & Inspection Services LTD Company

Al-Burjesia, Basra-Iraq
+9647703178132
+9647823386633
http://www.ras-iq.com
info@ras-iq.com

VISUAL & MAGENTIC PARTICLE INSPECTION REPORT

Certificate No: RAS-Y-261030017 **Date:** 10/10/2026
Customer: BMC Company **Due Date:** 09/04/2027
Location: Iraq- Basra

Name and Address of Owner
OM-QASER

Description
MPI of Structural Steel Support Assembly And Pipe-Mounted Structural Support Assembly



Area of Examination:
(20) Welded joints of the structural steel assemblies, bracing-to-main-frame connections, reinforcement plate welds, pin-hole connection areas, support-to-pipe welded joints, attachment brackets.
Model: RH 28
.Serial Number: 81D003

Inspection Result:

VISUAL AND MAGNETI PARTICLE INSPECTION (MPI) HAD BEEN DONE ON WELD & CRITICAL AREAS FOR THE ABOVE DESCRIBSION
AND FOUND
VISUALY: SURFACE INSPECTION OF WELDING…. **(ACCEPTED)**
M.P.I: FREE FROM SURFACE CRACKS OR OTHER DISCONTINUNTIES OF INSPECTION... **(ACCEPTED)**

Inspection Method
1 - NDT (MPI Test) & Visual Test

Final Results
PASSED

NDT DETAILS

Equipment Type: YOKE S/N: A12.512	**Standard: ASTM E709 | Method: WET**
Procedure: RAS-T-21090008	**Indicator: MAG INK**

Recommendation of Certificate

This is to certify that the undersigned, a competent inspector, did attend the site for testing to examine and ascertain that this **pipe assembly And Structural Steel Support** is safe for the intended use with the limits specified providing

Name & Qualifications of person making this report: AHMED YAHYA

Name of person authenticating this report:: MUSTAFA SALMAN